

A-05 Tri Co/Cheese Country Bridge #47

State of Wisconsin  
 Department of Natural Resources  
[dnr.wi.gov](http://dnr.wi.gov)

**Motorized Recreation Grant Application**

**For:** (Choose all that apply)

Form 8700-159 (R 02/2024)

Page 1 of 5

**Due Date: April 15**

- ATV/UTV Trail Aid
- Snowmobile Trail Aid

**Notice:** Completion of this form is required under Wisconsin Statutes 23.09(26) and 23.33. Failure to complete this form will result in denial of financial assistance. Personally identifiable information found on this form is not intended to be used for any other purpose. The Department of Natural Resources (DNR) may provide this information to requesters as required by Wisconsin's Public Records law (ss. 19.31 – 19.39, Wis. Stats.).

**Instructions:** Applications may combine more than one source of funds. They may be submitted for consideration of traditional ATV, UTV, Snowmobile and Motorized Stewardship funding. Submit one copy of all forms and attachments. See Page 2 for necessary attachments. Send applications to your [Community Services Specialist](#).

DNR Use Only	
Category	Number

**Section 1: Applicant Information**

Applicant / Organization Name Tri-County Trail Commission			Check Recipient: Individual other than authorized individual to act on behalf of the applicant. <input checked="" type="checkbox"/> Select if the same as applicant.		
Individual Authorized to Act on Behalf of Applicant per Resolution Max Blackburn			Check Recipient Name (Name to Appear on Check) Max Blackburn		
Title Tri-County Trail Coordinator			Title Tri-County Trail Coordinator		
Address 700 Main Street			Address 700 Main Street		
City Darlington	State WI	ZIP Code 53530	City Darlington	State WI	ZIP Code 53530
Telephone Number (608) 776-4893		Email Address trails@lafayettecountywi.org			

**Section 2: Project Information Required for all Projects**

Project Title Cheese Country Trail Bridge #47 Replacement					Current Funded Miles	New Miles (if applicable)
County Green	Township 01 N	Range 7	Section 4	¼ ¼ SE	¼ SW	GPS Coordinates: Lat. 42.5593442 Long. -89.675092

**Project Description Summary**

Proposed project is the complete replacement of Bridge #47 on the Cheese Country Trail over the Honey Creek in Green County. Project scope is to include removing deteriorated components and replacement with a new structure.

During a routine bridge inspection, major deficiencies were found in the bridge structure requiring closing the structure to any use and continues to be closed.

Currently here is the breakdown of the request from all grant programs:

RTP = \$100,000.00 (17%)  
 ATV/UTV = \$237,676.50 (41.5%)  
 Snowmobile = \$237,676.50 (41.5%)

I certify that all maintenance land use agreements are on file.

**Estimated Cost**

Maintenance	Acquisition	Insurance	Development	Bridge Rehab.	Trail Rehab.	Total Estimated Cost
				\$575,353.00		\$575,353.00
Leave Blank – DNR Use Only						

**Applicant Certification**

Printed Name of Authorized Official Max Blackburn	Official's Title Tri-County Trail Coordinator
--	--

As the applicant's authorized official, I certify that, to the best of my knowledge, the information in this application is true and correct.

*Max Blackburn*  
 \_\_\_\_\_  
 Signature of Authorized Official

2/27/2026  
 \_\_\_\_\_  
 Date Prepared

**Appendix A – Required for Bridge Rehab/Replace, New, or Reroute with New Bridge**

Bridge Rehab/Replace     New Bridge     Reroute with new bridge

County Green	Township 01 N	Range 7	<input checked="" type="radio"/> E <input type="radio"/> W	Section 4	¼ ¼ SE	¼ SW	GPS Coordinates: Lat. 42.5593442 Long. -89.675092
Water Body Name Honey Creek				Bridge Name Bridge #47		County Inventory Number #47	
Funded Trail Name or Number (SNARS if applicable) Cheese Country Trail				Has this bridge site ever received development or rehabilitation funds in the past? <input type="radio"/> Yes <input checked="" type="radio"/> No Year: _____ \$ _____			
Bridge is located on: <input checked="" type="radio"/> Private property <input type="radio"/> Public property				Old Bridge/Culvert Size 12' X 155'			
				New Bridge/Culvert Size 12' X 155'			
Landowner Where Bridge is Located Pecatonica Rail Transit Commission				Telephone Number		Length of Trail Use Agreement (5 year minimum) Non-Expiring	
Current maximum load 25,000 lbs.		Age of Bridge 50+		Bridge Material			
Proposed maximum load 25,000 lbs.		Wood foundations and superstructure					
Sponsoring Club Name Tri-County Trail Commission				Club Contact Max Blackburn		Telephone Number (608) 776-4893	
Do you have your trail bridges posted as to maximum load? <input type="radio"/> Yes <input checked="" type="radio"/> No				What is the maximum load of the other bridges on the system if groomed with this bridge?			
What is the weight of your puller & drag/grading equipment? ~25,000				At this time, maximum loads on the trail system are variable due to varying conditions of bridges.			
What other recreational trail uses are planned for this bridge? Pedestrian, bicycle and e-bicycle							
If there are other Recreational uses planned, how much of the bridge cost will be paid for by non-snowmobile or non-ATV users? None.							
<input type="radio"/> Yes <input checked="" type="radio"/> No Have you contacted your local <a href="#">DNR Water Management Specialist (WMS)</a> regarding a permit? <input checked="" type="radio"/> Yes <input type="radio"/> No Is a permit needed? (Please provide any written correspondence from WMS.) <input type="radio"/> Yes <input checked="" type="radio"/> No Have you contacted your County Zoning Dept. regarding a floodplain determination? <input checked="" type="radio"/> Yes <input type="radio"/> No Will an H & H (hydrologic and hydraulic) study be required?							

**Bridge Project Detailed Description**

Proposed project is the complete replacement of Bridge #47 on the Cheese Country Trail.

In a routine bridge inspection completed by NBI Engineering, critical deficiencies were found in the foundation of the bridge resulting in the closure of this bridge.

Currently we are looking at proposing a new 12' X 155' new bridge structure. All degraded wooden components will have to be replaced. Since the structure is so old, changes will have to be evaluated for floodplain compliance.

A pre-application meeting will be scheduled in the immediate future with DNR WMS for permitting requirements and with county zoning to work through floodplain permitting and H&H work that will be needed.

**Appendix A (continued)**

**Summarize Costs in Appropriate Categories:**

**Bridge Structure**

	Quote 1	Quote 2
	<input checked="" type="radio"/> Steel <input type="radio"/> Wooden	<input type="radio"/> Steel <input type="radio"/> Wooden
Bridge Dimensions:	_____	_____
Bridge Manufacturer:	TBD _____	_____
Design Weight Load	_____ lbs.	_____ lbs.
Cost of Structure:		
1. Engineering	\$ <u>71,808</u>	\$ _____
2. Structure	\$ <u>422,400</u>	\$ _____
<b>Subtotal</b>	<b>\$ <u>494,208</u></b>	<b>\$ _____</b>

	Quote 1	Quote 2
	<input checked="" type="radio"/> Contractor or <input type="radio"/> Sponsor Estimate	<input type="radio"/> Contractor or <input type="radio"/> Sponsor Estimate
<b>Installation Costs:</b>		
1. Engineering	\$ <u>61,645</u>	\$ _____
2. Site Preparation	\$ _____	\$ _____
3. Abutments	\$ _____	\$ _____
4. Pilings/Piers	\$ _____	\$ _____
5. Approaches	\$ _____	\$ _____
6. Riprap	\$ _____	\$ _____
7. Labor	\$ _____	\$ _____
8. Equipment Rental	\$ _____	\$ _____
9. Culverts	\$ _____	\$ _____
10. H & H Study	\$ _____	\$ _____
11. Wetland Delineation	\$ _____	\$ _____
12. Other <u>Soil Borings</u>	\$ <u>19,500</u>	\$ _____
<b>Subtotal</b>	<b>\$ <u>81,145</u></b>	<b>\$ _____</b>
<b>Total Cost</b>	<b>\$ <u>575,353</u></b>	<b>\$ _____</b>


*(includes construction labor to see attached cost estimate)*

**For the application grant, you must take the lowest of the two quotes.**

**Entire Deck and Railing Projects**       Contractor    Sponsor    Club

Bridge Dimensions:	_____
Design Weight Load	_____ lbs.
1. Materials	\$ _____
2. Labor	\$ _____
<b>Total</b>	<b>\$ _____</b>





Duncan Hill Road  
Ridge Road  
County Highway Y  
County Highway M  
Dog Hollow Road  
Smock Valley Road  
Ridge Road  
Buckhorn Road  
County Highway MN  
Charvic Street  
Pine Tree Road  
Cadiz Springs Rd  
Ullom Road  
Keller Rd 11  
Steiner Road  
Franklin Road  
Melvin Road  
Honey Creek Road  
Woodman Road  
Falk Rd  
Hiawatha Road  
Loop Road  
Klondike Road  
Dolan Road  
Voegli Road  
County Highway J  
County Highway 81  
Iliff Road  
County Road N  
County Highway DR  
County Highway 69  
Utility Lane  
Tullmar Lane  
Grand View Lane  
Youth Cabin Road  
Wald Road  
Rufenacht Road  
Pond View Road  
7th Street  
6th Street  
1st Avenue  
6th Street  
14th Avenue  
18th Avenue  
N 20th Avenue  
9th Street  
Sunrise Court  
County Highway 59  
31st Avenue  
West 17th Street  
18th Street  
Bartt Court  
Canton Drive  
Patterson Road  
West 17th Street  
18th Street  
2nd Avenue  
7th Avenue  
11th Avenue  
14th Avenue  
18th Avenue  
18th Street  
26th Avenue  
Sunrise Court  
31st Avenue  
Asmus Road  
Mings Road  
Jeffery Road  
Davis Road  
County Highway M  
East Park Street  
Pils Road  
Butts Road  
Butts Road  
Mellenberger Road  
Allen Road  
County Highway B  
County Highway HK  
Bartelt Road  
Figi Road  
Lawver Road  
Nursery Road  
Lawyer Road

Bridge #47

**Guidelines for Applicant**


Complete this form for each bridge structure you are submitting a grant application for. Provide any additional documents not requested on application checklist to substantiate your points, including actual deeded easements.

This ranking tool is used for both **Snowmobile** and **ATV/UTV** Trail Aids programs, though each program may score things differently. If you are seeking funding from BOTH programs for a dual use bridge, please score ALL questions


Category		Possible Points	Snow Points	ATV/UTV Points
<b>1</b>	<b>Condition of the Structure</b> (max of 10 points)			
	Has a certified bridge inspection report that supports the project & demonstrates need. Copy of report needed. <b>Snowmobile Funded Projects</b>	10	10	
	Calculation: 10 minus NBI Rating Score (0-9) <b>ATV Funded Projects</b> Use overall NBI # if provided, or an average of the components. Redecking projects should just use the deck NBI #.	10		9
<b>2</b>	<b>Permits</b> (maximum points 4)			
	Consultation with DNR Water Mgmt Specialist has occurred & permit is likely, if needed	1	-	-
	Permit in hand / Bridge already permitted	3	-	-
<b>3</b>	<b>Funding</b> (maximum points 2) Has an application been submitted for other funding			
	50% or greater from other funding source(s)? (includes 50/50 Snow/ATV projects)	2	2	2
	11% - 49% from other funding source(s)?	1	-	-
<b>4</b>	<b>Length of Written Easements or Land Use Agreement</b> (max points 5)(ch. 23.09(26)(am)1 WI Stats)			
	On public land (County, State, Federal)	5	5	5
	10 or more year <b>deeded easement</b> on private land or other public land, for <u>all portions of that trail to the nearest road on each side of the bridge</u>	5	-	-
	3-9 year <b>deeded easement</b> on private land or other public land, for <u>all portions of that trail to the nearest road on each side of the bridge</u>	4	-	-
	10 or more year <b>deeded easement</b> on private land or other public land, for <u>just the bridge site</u>	3	-	-
	3-9 <b>deeded easement</b> on private land or other public land, for just the bridge site	2	-	-
	10 or more year land use agreement (LUA, not deeded) on private land or other public land	1	-	-
	3-9 year land use agreement (LUA, not deeded) on private land or other public land	0	-	-
<b>5</b>	<b>Miles Impacted</b> – How many miles will need to rerouted if the structure is not replaced? Measured from nearest intersection on both sides of the bridge. (max 4 points)			
	Less than 20 miles <b>Snowmobile Funded Projects</b>	1	1	
	20 miles or more <b>Snowmobile Funded Projects</b>	3	-	
	No other snowmobile trails connect. <b>Snowmobile Funded</b> Explain:	4	-	
	For ATV/UTV projects, describe the relocation (on routes? Trail?) Include sketch/map		✓	
<b>6</b>	<b>If ATV/UTV, Seasons of Use</b> (max 3 points)			
	Year-Round or Summer Only <b>ATV/UTV Trail</b>	3		3
	Winter Only <b>ATV/UTV Trail</b>	1		-
	<b>DEDUCTIONS</b>			
<b>7</b>	<b>County Active Project Deduction</b> (maximum deduction 1 point) A snowmobile active project is one that has exceeded it's initial grant period.			
	Two or more active projects - deduct 1 point	-1	-1	
<b>GRAND TOTAL</b>			17	14



Trail re-route because of #47 closure.



Bridge is located in the purple highlighted area. This area is within FEMA regulated floodplain.




**Legend:** (some map layers may not be displayed)

- Wetland Class Areas
- Wetland Indicators
- Rivers and Streams
- Intermittent Streams
- 24K Intermittent Streams
- 24K Streams and Rivers
- Cities, Towns & Villages**
- City
- Civil Town
- Municipalities**
- City
- Civil Town
- County and Local Roads**
- Local Road
- County Boundaries
- WI State Boundary

**Notes:**

Bridge is located with green line



Service Layer Credits:  
Wetland Indicators & Soils: Surface Water Data Viewer Team, DNR Basic Feature VTL (WTM): Wisconsin Department of Natural Resources, GIS Section, Latest Leaf Off; Surface Water: WiDNR, USGS, and other data, Wetland Inventory NWI (Dynamic): Calvin Lawrence, Dennis Weise, Nina Rihn

Map projection: NAD 1983 HARN Wisconsin TM

This map is a product generated by a DNR web mapping application.

This map is for informational purposes only and may not have been prepared for or be suitable for legal, engineering, or surveying purposes. The user is solely responsible for verifying the accuracy of information before using for any purpose. By using this product for any purpose user agrees to be bound by all disclaimers found here: <https://dnr.wisconsin.gov/legal>

Date Printed: 2/27/2026 12:51 PM

Bridge ID / Structure No.  <b>Bridge #47</b>	<b>Inspection Date:</b>	11.24.2025
	<b>Inspection TL:</b>	Nate Miller, PE
	<b>NBI Project No:</b>	2503501

Inspection Report for  
**Bridge #47**  
Cheese Country Trail over Honey Creek



**Executive Summary**

**Recommended Inspection Frequency:**

- Not Applicable – **Recommend Immediate Closure.**

**Estimated Remaining Longevity:**

- The efforts required to return the bridge to service are likely not economically feasible given the extent of the observed damage and complexities of the required repairs. Additional investigations would be required to determine the feasibility of a comprehensive rehabilitation plan.

**Summary of Channel Conditions:**

- **The west embankment is in a state of imminent failure.** Extensive erosion at the toe of the west embankment has caused a 15ft-20ft vertical embankment to be retained by remnants of a critically decayed timber wall. Failure of the embankment would likely destabilize Pier W2, resulting in a full, or partial, collapse of the bridge.

**Summary of Structural Conditions:**

- Severely decayed timber components observed throughout the bridge. Several beams show signs of horizontal shear cracking. Multiple piles and pile caps have significant section losses, are vertically split, and isolated piles show signs of crushing. This bridge is particularly vulnerable to collapse due to height and configuration of the piers.

**Maintenance/Repair Recommendations:**

- **Owner notified of Critical Finding: Bridge should be immediately closed to all traffic.**

*Nate Miller*

Nathan W. Miller  
Bridge Inspection Team Leader, Inspector Number: 9601

11.24.2025

Date

<b>Bridge ID / Structure No.</b>  <b>Bridge #47</b>	<b>Inspection Date:</b> 11.24.2025
	<b>Inspection TL:</b> Nate Miller, PE
	<b>NBI Project No:</b> 2503501
Facility Owner/Managing Agency: Tri-County Trails Commission	Representative: Max Blackburn
Email: trails@lafayettecountywi.org	Phone: 608-776-4893

**Summary of Inspection Intent, Procedures, and Limitations**

- NBI Engineering Services personnel visited the above referenced structure to observe the existing conditions and collect information on behalf of The Tri-County Trail Commission. The purpose of this inspection was to determine the physical and functional condition of the bridge.
- Observations have been limited to readily available surface conditions. No destructive or invasive testing procedures, load rating, or detailed measurements have been performed as part of this inspection. NBI Engineering Services reserves the right to revise our opinions if additional evidence becomes available.
- Timber conditions were evaluated by visual inspection and acoustic sounding.
- Due to access limitations, assessment of components above 6 ft above grade was limited primarily to visual observation.
- Beams and piers inspected from the ground and deck via pole cam.
- The facility was open to traffic during the inspection.
- No plans or prior inspection information for the structure have been provided.

Time Log    Onsite: 8.0 Hours *Inspection Started 11/21/2025 – Completed 11/24/2025.*

**Inventory Data**

Feature On:	Cheese Country Trail	Feature Under:	Honey Creek
Lat./ Long.:	42.5934, -89.6751		
Orientation:	Traffic Direction: EB/WB	Channel Flow:	Upstream: North - Downstream: South

**Structure Type**

No. Spans:	11	Wearing Surface:	Concrete Deck
Deck	Cast-In-Place Concrete over Timber Cross-Ties		
Superstructure	3-Ply Timber Beams	No. Beam Lines:	2
Substructure	Abutments: Timber Pile with Timber Backwall Plank		
	Pier(s): Timber Pile Bent		

**Geometric - Dimensions are approximate.**

Width (O-O):	12.0'	Deck Length (O-O):	155.0'
Width (C-C):	10.1'	Span Length(s):	14.0'/13.5'/13.5'/14.0'/14.0'/14.0'/14.0'/14.0'/14.0'/14.5'/13.0'

**Assessments**

Quantity in CS

Assessment	Description	UOM	Total	1	2	3	4	Comments
9001	Drainage -Ends of Structure	EA	4		2	2		Well Vegetated. West Approach Undermined.
9004	Drainage - Structure	EA	0					No Bridge Deck Drains.
9030	Signs - Object Markers	EA	4	3		1		Present at All 4 Corners.
9035	Signs - Other	EA	2		1		1	"BRIDGE AHEAD". W: Missing.
9035	Signs - Other	EA	2	1		1		"15 MPH ON BRIDGE".
9041	Slope Protection -Bare	EA	2		1		1	Natural Earth Embankments. Imminent Failure of West Embankment.
9324	Approach Roadway -Gravel	EA	2	2				Freshly Graded.

<b>Bridge ID / Structure No.</b>  <b>Bridge #47</b>	<b>Inspection Date:</b>	11.24.2025
	<b>Inspection TL:</b>	Nate Miller, PE
	<b>NBI Project No:</b>	2503501

---

**SNBI Condition Ratings & Commentary**

---

**Deck (C.01) | 4 | Poor Condition – Deteriorating**

1. Concrete slab (wearing surface) over timber crossties(deck).
2. Moderate wear of concrete throughout wearing surface, most pronounced along wheel lines. Multiple unsealed moderate/wide width transverse cracks throughout concrete slab.
3. Timber crossties decayed and split at ends. Signs of decay throughout all timber components. Timber preservative treatment is no longer effective.

Maintenance/Repair Recommendations

No feasible rehabilitation options to extend longevity of component.

---

**Railings (C.05) | 5 | Fair Condition – Stable**

1. (3) rows of W-beam bridge rail supported by angled timber posts.
2. Initial signs of incipient decay of timber components. Timber preservative treatment appears marginally effective.
3. Isolated areas of minor damage to w-beam rails.

Maintenance/Repair Recommendations

No recommended maintenance/repair recommendations.

---

**Transition Railings (C.06) | N/A | Not Applicable**

---

**Joints (C.08) | N/A | Not Applicable**

---

**Superstructure (C.02) | 3 | Serious Condition - Deteriorating**

1. (2) lines of timber beams each comprised of (3) through-bolt connected laminations.
2. Beams decayed +/-75% throughout with widespread prominent checking and generally appear hollow when sounded. Widespread areas of horizontal shear cracking.
3. No readily evident signs of crushing.
4. Beams are highly susceptible to overload damage.

Maintenance/Repair Recommendations

No feasible rehabilitation options to strengthen or extend longevity of component.

---

**Bearings (C.07) | N/A | Not Applicable**

---

<b>Bridge ID / Structure No.</b>  <b>Bridge #47</b>	<b>Inspection Date:</b>	11.24.2025
	<b>Inspection TL:</b>	Nate Miller, PE
	<b>NBI Project No:</b>	2503501

**Substructure (C.03) | 1 | Imminent Failure – Deteriorating**

**Abutments:**

1. Driven timber piles, timber pile caps, and timber backwall plank.
2. Decayed timber components throughout with no signs of crushing.
3. Caps are decayed and generally appear hollow when sounded with an estimated 75% loss of section throughout with more advanced decay at the ends. Widespread areas of checking and full depth splitting.
4. Piles: Exposed bearing piles sound hollow with an estimated 75%-90% loss of section with several split piles.

**Pier(s):**

1. Piers W1-W3 and W7-W10: Driven timber piles with timber pile caps.
2. Piers W4-W6: Poured concrete footings with timber sill beams under timber pile bents with timber pile caps.
3. **The west embankment is in a state of imminent failure which could destabilize Pier W2 and cause a full, or partial collapse of the bridge.**
4. Decayed timber components throughout with signs of crushing.
5. Multiple caps are severely decayed and are splitting/separating.
6. The bottom sill beams are severely decayed with the sill crushing in Pier W6.
7. Piles are decayed with significant section losses throughout with multiple piles visibly hollow and split. Pile S5 in Pier W7 is starting to crush. The tapered driving tip of Pile S2 in Pier W7 is exposed, indicating negligible pile embedment.

Maintenance/Repair Recommendations

No feasible rehabilitation options to strengthen or extend longevity of component.

**Channel (C.09) | 1 | Imminent Failure - Deteriorating**

1. Embankment Erosion: **The west embankment is in a state of imminent failure.** Severe erosion at the toe of the west embankment has caused a 15ft-20ft vertical embankment to be retained by remnants of a critically decayed timber wall. *See included channel profile sketches included as Figures 1-3, included with this report.* Erosion at Pier W7 has exposed the tapered pile tip of Pile W2.
2. Drift: Flood debris caught on upstream face of piers.
3. Channel Change: Waterway flows through spans W4-W6 and around Piers W3-W6.
4. Adequacy of Opening: No readily visible signs of overtopping.

Maintenance/Repair Recommendations

*See Channel Protection.*

**Channel Protection (C.10) | 1 | Imminent Failure - Deteriorating**

1. Vegetation: Channel is well vegetated.
2. Channel Protection: Failing remnants of a critically decayed timber wall at the west embankment between Piers W2-W3. Failure of the timber wall is expected to result in the collapse of the west embankment, which may cause the collapse of Pier W2. Stone masonry wall at east embankment between Piers W6-W7 is in fair condition.

Maintenance/Repair Recommendations

Comprehensive channel stabilization efforts may be possible, however additional investigations would be required to determine the feasibility of a comprehensive rehabilitation plan.

**Scour (C.11) | 1 | Imminent Failure - Deteriorating**


1. Streambed Scour: Natural earthen streambed is moderately prone to scour. Negligible channel scour observed throughout opening.

Maintenance/Repair Recommendations


*See Channel Protection.*

**Channel Profile Sketches**


1. Measurements were collected with a weighted tape measure over the bridge rail. Distances are referenced from the top of the pile caps and should be considered approximate. Cross bracing locations (when shown) are approximate and are for reference purposes only.
2. No information has been provided to establish the original channel profile. Locations shown below have been approximated based on observed conditions, location of pier bracing, and the presence of a cast-in-place concrete block in the channel. The original channel profile may vary considerably from illustrated representation which has been included for reference purposes only.
3. Pile tip elevations are unknown and have been shown to a depth of 40 feet below the top of pile caps. This should be considered as the maximum possible depth of penetration due to the presence of readily visible bedrock in the streambed. Pile tip elevations likely vary throughout the bridge and shallower pile elevations should be assumed. The tapered driven tip of Pile S2 in Pier W7 is exposed, indicating negligible remaining embedment, and therefore includes a tip elevation shallower than is shown in Figure 1, below (see Photo 49).



**Figure 1. Downstream Channel Profile-Full Bridge Length**



**Figure 2. Downstream Channel Profile-Spans W1-W4**



**Figure 3. Upstream Channel Profile-Spans W1-W4**

<b>Bridge ID / Structure No.</b>	<b>Bridge #47</b>	<b>Inspection Date:</b>	11.24.2025
		<b>Inspection TL:</b>	Nate Miller, PE
		<b>NBI Project No:</b>	2503501

## Deck

**Deck Rating:** **4**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4	
Wearing Surface	8514	<b>Wearing Surface-Concrete Overlay</b> <i>Retrofit C-I-P concrete slab over timber cross ties.</i>	<b>6</b>	SF	1860		1800	60	
		WS-Crack	SF			900	60		
		CS3: 5 transverse lines of moderate/wide width cracks across width of deck.							
	8911	WS-Abrasion/ Wear/ Rutting or Loss of Friction CS2: Concrete worn to large aggregate at wheel lines. Outside edges of deck covered with crushed stone across 50% of length.	0			900			
Deck	31	<b>Deck-Timber</b> <i>Timber Cross ties.</i>	<b>4</b>	SF	1550		775	775	
		TBR-Checks/ Shakes/ Cracks/ Splits/ Delamination	SF			775	775		
		CS2/CS3: Signs of timber decay throughout cross ties-more severe at ends. Assume 25% section loss across all cross ties. CS3: Full depth splitting and/or decay at east end 3ft of 60% of cross ties. Assume 10% split for full length.							
	9004	<b>Drainage-Structure</b> None. No bridge deck drains.	<b>N</b>	EA					

## Bridge Railing

**Bridge Railing Rating:** **5**

**Bridge Railing Transition Rating:** **N**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4	
Railing	330	<b>Metal Bridge Railing</b> <i>(3) rows of W-beam bridge rail supported by angled timber posts.</i>	<b>5</b>	LF	310		260	50	
		TBR-Decay/ Section Loss/ Abrasion/ Wear	LF			260			
		CS2: Timber posts show initial signs of incipient decay and weather checking.							
		Steel Protective Coating	LF					50	
		CS2: Rail galvanizing substantially effective - chalking/surface dulling. CS3: Faded galvanizing/tightly adhered surface corrosion of rails (50-LF).							
	7000	Damage CS1: Isolated minor collision damage to rail.	LF						

## Bridge Joints

**Bridge Joints Rating:** **N**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4
Joints		<b>Joint Type</b> <i>None. Concrete bridge deck runs continuously over length of structure.</i>	<b>N</b>	LF				
		Defect	LF					
		N/A						

<b>Bridge ID / Structure No.</b>	<b>Bridge #47</b>	<b>Inspection Date:</b>	11.24.2025
		<b>Inspection TL:</b>	Nate Miller, PE
		<b>NBI Project No:</b>	2503501

### Superstructure

**Superstructure Rating:** **3**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4
Superstructure	111	<b>Superstructure-Timber-Open Girder/ Beam</b> <i>2 beam lines of 3-ply timber beams.</i>	<b>3</b> LF	310			154	<b>156</b>
	1140	TBR-Decay/ Section Loss/ Abrasion/ Wear CS3/CS4: All beams decayed and sound hollow with an estimated +/-75% loss of section.	LF				77	
	1150	TBR-Checks/ Shakes/ Cracks/ Splits/ Delamination CS3: Prominent checking (+/- 3/16") throughout length of beams. CS4: Prominent checking/horizontal shear cracking (> 3/16") - Assume 50% of beams:	LF				77	<b>156</b>
	1020	Connection Through-bolts appear intact and functioning as intended.	LF					
	1900	Distortion Beam appear properly aligned with no readily visible signs of distortion.	LF					
	7000	Damage No readily visible signs of damage. Decayed timber beams are highly susceptible to overload damage.	LF					
		Protective Coatings: CS4: Timber preservative treatment ineffective.						

### Bearings

**Bearing Rating:** **N**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4
Bearings		<b>Bearing Type</b> <i>Timber beams bear directly on timber caps.</i>	<b>N</b> EA					
	2210	BRG-Movement N/A	EA					
	2240	BRG-Loss of Bearing Area N/A	EA					

<b>Bridge ID / Structure No.</b>	<b>Bridge #47</b>	<b>Inspection Date:</b>	11.24.2025
		<b>Inspection TL:</b>	Nate Miller, PE
		<b>NBI Project No:</b>	2503501

## Substructure

**Substructure Rating:** 1

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4	
Abutments	216	<b>Substructure-Timber-Abutment</b> <i>Timber Backwall Plank - Timber pile with backwall plank abutment.</i>	4	LF	28			28	
		TBR-Decay/ Section Loss/ Abrasion/ Wear	LF				14		
		CS3: Timber plank showing signs of incipient decay.							
		4000 Settlement	LF						
		No readily visible signs of settlement.							
		6000 Scour	LF					14	
		CS1: Both abutments beyond channel flow. No signs of undermining of backwall plank.							
		Protective Coatings: CS4: Timber preservative treatment ineffective.							
	235	<b>Substructure-Timber-Pile Cap-Abutment</b> <i>Timber Pile Cap - Timber pile with backwall plank abutment.</i>	3	LF	28			14	14
		TBR-Decay/ Section Loss/ Abrasion/ Wear	LF					14	14
	CS3/CS4: Caps sound hollow with soft/easily dented shells-estimated +/-75% decay/section loss-more severe at ends. Prominent horiz. and vert. checking throughout. No definitive signs of crushing. Vertical split throughout length of caps-most severe at north ends of both caps.								
	Protective Coatings: CS4: Timber preservative treatment ineffective.								
228	<b>Substructure-Timber-Pile-Abutment</b> <i>Timber Piles - Timber pile with backwall plank abutment.</i>	3	EA	10			5	5	
	TBR-Decay/ Section Loss/ Abrasion/ Wear	EA					5	5	
	[5] Bearing piles per abutment. Less than 2ft of piles exposed.								
	CS3/CS4: Tops of piles sound hollow with moderate to wide checking throughout. No definitive signs of crushing. All piles decayed with +/- 75% loss of section. Multiple piles split and decayed >75%.								
	Protective Coatings: CS4: Timber preservative treatment ineffective.								
Wingwalls	8400	<b>Wingwall-Timber</b> <i>Integral timber wingwalls. Backwall plank extends beyond bearing piles-no supplemental wingwall piles.</i>	4	EA	4			4	
		WW-Deterioration	EA				4		
		CS3: Wingwall plank showing signs of incipient decay.							
		6000 Scour	EA						
		CS3: Erosion has undermined the ends of SW/NW/NE wingwall planks.							
	Protective Coatings: CS4: Timber preservative treatment ineffective.								

<b>Bridge ID / Structure No.</b>	<b>Bridge #47</b>	<b>Inspection Date:</b>	11.24.2025
		<b>Inspection TL:</b>	Nate Miller, PE
		<b>NBI Project No:</b>	2503501

Pier(s)	235	<b>Substructure-Timber-Pile Cap Pier</b>	<b>2</b>	LF	150			30	120	
		<i>Timber Pile Cap - Timber pile bent pier.</i>								
		TBR-Decay/ Section Loss/ Abrasion/ Wear		LF				30	<b>120</b>	
		1140	Caps decayed and sound hollow throughout length with prominent horiz. and vert. checking/splitting throughout-more severe at ends. Visual assessments for elements above 6ft. CS3: Full depth split (<1/4") wide, +/- 50% decay. Piers: W2/W9. CS4: Full depth split (>1/4") wide, >50% decay. Piers: W1/W3/W4/W5/W7/W8. CS4: Bottom sill beam in Pier W6 decayed +/-90% and starting to crush under piles. (Pier W6 pile cap CS3).							
		Protective Coatings: CS4: Timber preservative treatment ineffective.								
		228	<b>Substructure-Timber-Pile-Pier</b>	<b>1</b>	EA	60			23	37
			<i>Timber Piles - Timber pile bent pier.</i>							
			TBR-Decay/ Section Loss/ Abrasion/ Wear		EA				23	<b>30</b>
			1140	[6] Bearing piles per pier. Visual assessments for elements above 6ft. CS3/CS4: Piles sound hollow with prominent vertical checking/splitting throughout. Pile shells soft/easily damaged. [24] Piles vertically split (1/4"-3"). Pier W7-Pile S5 starting to crush at top under cap. Multiple piles poorly aligned under caps (1"-6" offset)-tops of offset piles visible hollow and decayed +/-90%. Assume 50% of piles in CS4.						
			4000	Settlement		EA				
			No readily visible signs of settlement.							
			Scour		EA				<b>7</b>	
		6000	CS4: Imminent failure of embankment at Pier W2 (6-Piles). Tapered driving tip of Pile S2 in Pier W7 exposed. <i>See Channel/Channel Protection descriptions for additional information.</i>							
	Protective Coatings: CS4: Timber preservative treatment ineffective.									

Bridge ID / Structure No.

# Bridge #47

Inspection Date: 11.24.2025

Inspection TL: Nate Miller, PE

NBI Project No: 2503501

Inspection Photos:

All photos taken at above referenced inspection date unless noted otherwise.



Photo 1 – Trail View Looking West.



Photo 2 – Trail View Looking East.



Photo 3 – Upstream Looking North.



Photo 4 – Downstream Looking South.



Photo 5 – Side View Looking North.



Photo 6 – Side View Looking South.

Bridge ID / Structure No.

Bridge #47

Inspection Date: 11.24.2025

Inspection TL: Nate Miller, PE

NBI Project No: 2503501



Photo 7 – West Embankment Looking North.



Photo 8 – West Embankment Looking South.



Photo 9 – West Embankment Looking East.



Photo 10 – West Embankment Looking South.



Photo 11 – West Embankment Looking Southwest .



Photo 12 – East Embankment Looking South.



Photo 13 – Northwest Embankment Looking East.



Photo 14 – West Embankment Looking North.



Photo 15 – West Abutment.



Photo 16 – West Abutment Cap Looking South.



Photo 17 – Northwest Wingwall.




Photo 18 – Northwest Wingwall.



Photo 19 – West Approach Looking South.



Photo 20 – West Approach Looking North.



Photo 21 – Southwest Wingwall.



Photo 22 – Southwest Wingwall.



Photo 23 – Pier W1 Looking East.



Photo 24 – Pier W1 Looking Northwest.



Photo 25 – Pier W1 Cap-South End.



Photo 26 – Pier W1 Cap-North End.



Photo 27 – Pier W1 Looking Southwest.



Photo 28 – Pier W1 Looking North.



Photo 29 – Pier W1-Pile S5-S3.



Photo 30 – Pier 2 W3-W2 Looking Southwest.



Photo 31 – Pier W3 Looking South.



Photo 32 – Pier W3 Looking West.



Photo 33 – Pier W4 Looking East.



Photo 34 – Pier W4 Looking West.



Photo 35 – Pier W4 Looking South.



Photo 36 – Pier W4 Looking North.



Photo 37 – Pier W5 Looking East.



Photo 38 – Pier W5-Pile S5 Looking East.



Photo 39 – Pier W5 Looking North.



Photo 40 – Beams Over Pier W5 Looking East.



Photo 41 – Pier W5 Looking West.



Photo 42 – Pier W6 Looking East.



Photo 43 – Pier W6-Pile S3.



Photo 44 – Pier W6 Bottom Sill-Pile S2.



Photo 45 – Pier W6 Looking West.



Photo 46 – Pier W6 Looking North.



Photo 47 – Pier W7 Looking East.



Photo 48 – Pier W7-Pile S1.



Photo 49 – Pier W7-Pile S2.



Photo 50 – Pier W7 Looking East.



Photo 51 – Pier W7 Looking South.



Photo 52 – Pier W7 Looking North.



Photo 53 – Pier W7 Looking Southwest.



Photo 54 – Pier W7-Pile S5.



Photo 55 – Pier W8 Looking East.



Photo 56 – Pier W8 Looking West.



Photo 57 – Pier W8 Cap-North End.



Photo 58 – Pier W8 Cap-North End.



Photo 59 – Pier W9 Looking East.



Photo 60 – Pier W9-Pile S4.



Photo 61 – Pier W9-Pile S1.



Photo 62 – Pier W9 Looking North.



Photo 63 – Pier W9-Pile S1.



Photo 64 – Pier W9-Pile S1.



Photo 65 – Span W9 Beams Looking South.



Photo 66 – Span W9 Beams Looking North.



Photo 67 – Pier W10 Looking East.



Photo 68 – Pier W10-Pile S2.



Photo 69 – Pier W10-Pile S2.



Photo 70 – East Abutment.

Bridge ID / Structure No.

**Bridge #47**

Inspection Date: 11.24.2025

Inspection TL: Nate Miller, PE

NBI Project No: 2503501



Photo 71 – East Abutment-South End.



Photo 72 – Northeast Wingwall.



Photo 73 – Northeast Wingwall.

-End of Report- *Additional Photos Available*