## #4 Oconto Nicolet ST Oconto River Bridge Redecking

State of Wisconsin Department of Natural Resources dnr.wi.gov

**Motorized Recreation Grant Application** For: (choose all that apply)

Form 8700-159 (R 02/2024)

Page 1 of 5

Due Date: April 15

Notice: Completion of this form is required under Wisconsin Statutes 23.09(26) and 23.33. Failure to complete this form will result in denial of

Instructions: Applications may combine more than one source of funds. They may be submitted for consideration of traditional ATV, UTV, Snowmobile and Motorized Stewardship funding. Submit one copy of all forms and attachments. See Page 2 for necessary attachments. Send applications to your Community Services Specialist.    Section 1: Applicant Information
Applicant / Organization Name  Oconto County  Individual Authorized to Act on Behalf of Applicant per Resolution  Monty Brink  Title  Forest, Parks and Recreation Administrator  Address  301 Washington St  Check Recipient: Individual other than authorized individual to act on behalf of the applicant.  Select if the same as applicant  Check Recipient Name (Name to Appear on Check)  Oconto County Treasurer  Title  Title  Treasurer  Address  301 Washington St
Oconto County  Individual Authorized to Act on Behalf of Applicant per Resolution  Monty Brink  Title  Forest, Parks and Recreation Administrator  Address  301 Washington St  Oconto County  Title applicant.  Select if the same as applicant  Check Recipient Name (Name to Appear on Check)  Oconto County Treasurer  Title  Treasurer  Address  301 Washington St
Individual Authorized to Act on Behalf of Applicant per Resolution  Monty Brink  Oconto County Treasurer  Title  Forest, Parks and Recreation Administrator  Address  Address  301 Washington St  Title  Treasurer  Address  Treasurer  Address  301 Washington St
Monty BrinkOconto County TreasurerTitleTitleForest, Parks and Recreation AdministratorTreasurerAddressAddress301 Washington St301 Washington St
Title Forest, Parks and Recreation Administrator Address Address 301 Washington St Title Treasurer Address 301 Washington St
Forest, Parks and Recreation Administrator  Address  Address  301 Washington St  Treasurer  Address  301 Washington St
Address Address 301 Washington St 301 Washington St
301 Washington St 301 Washington St
City State 7/P Code City State 7/P Code
James   James
Oconto   WI   54153   Oconto   WI   54143
Telephone Number Email Address
(920) 834-6995 monty.brink@co.oconto.wi.us
Section 2: Project Information Required for all Projects
Project Title Current Funded Miles New Miles (if applicable)
Nicolet State Trail Oconto River Bridge 111.43
County Township Range Section 1/4 1/4 GPS Coordinates:  © E
Oconto 28 N 18 OW 26 NW SE Long88.2754
Project Description Summary
Oconto County wishes to re-deck the Nicolet State Trail Bridge that is bridge number 23 on the DNR bridge inventory
list for Oconto County. Boards on the wear surface are pulling up and unable to be reattached due to loss of integrity of
the lower timber deck requiring a complete tear off of decking down to the girders and new decking.
Total Project Cost Estimate=\$800,000.00  RTP application-80%=\$250,000 cap  SNOWmobile 275,000
I certify that all maintenance land use agreements are on file.
Estimated Cost
Maintenance Acquisition Insurance Development Bridge Rehab. Trail Rehab. Total Estimated Co
Leave Blank – DNR Use Only
Leave Blank – DNR Use Only
Leave Blank – DNR Use Only  Applicant Certification  Printed Name of Authorized Official Official's Title

As the applicant's authorized official, I certify that, to the best of my knowledge, the information in this application is true and correct.

## Motorized Recreation Grant Application

Form 8700-159 (R 02/2024)

Page 3 of 5

Appendix A – Required for Bridge Rehab/Repla	ice, New, or Reroute with New Bridge	•							
⊠ Bridge Rehab/Replace       □ New Bridge	Reroute with new bridge								
	Section 1/4 1/4 GPS Coordinates:								
Oconto 28 N 18 OW	26 NW SE Lat. 44.8714 Long88.2754								
Water Body Name	(A)	County Inventory Number							
Oconto River	NST Oconto River Bridge	23							
Funded Trail Name or Number (SNARS if applicable)	Has this bridge site ever received development	ent or rehabilitation funds							
Nicolet State Trail- Gillett Trail 2	in the past?   Yes   No Year:	\$							
Bridge is located on: Private property	Old Bridge/Culvert Size 528'x10'	10007							
<ul> <li>Public property</li> </ul>	New Bridge/Culvert Size 528'x12'								
Landowner Where Bridge is Located	Telephone Number Length of Trail Us	se Agreement (5 year minimum)							
WI DNR 920-834-6995 Easement									
Current maximum load <u>Unknown</u> lbs. Age of E	Bridge Material								
Proposed maximum load 25,000 lbs. 107	Steel Girder, wooden decking								
Sponsoring Club Name	Club Contact Telep	phone Number							
Gillett SnowATV Riders	Perry Gilbertson	920-615-5880							
Do you have your trail bridges posted as to maximum load?  Yes  No	What is the maximum load of the other bridges groomed with this bridge?	on the system if							
What is the weight of your puller & drag/grading equipment?	Unknown								
13,800 lbs									
What other recreational trail uses are planned for this bridge?									
ATV, Snowmobile, Non-motorized-hiking, biking, hor									
If there are other Recreational uses planned, how much of the	bridge cost will be paid for by non-snowmobile	or non-ATV users?							
RTP-80%= \$640,000.00	- W								
● Yes   ○ No Have you contacted your local <u>DNR Water</u>	Management Specialist (WMS) regarding a peri	mit?							
○ Yes • No Is a permit needed? (Please provide any w	vritten correspondence from WMS.)								
Yes	ept. regarding a floodplain determination?								
Yes No Will an H & H (hydrologic and hydraulic) st	udy be required?								

## Bridge Project Detailed Description

Removal of all decking materials down to steel girders and replace and widen to 12' width and install new railings. Repair crack in brearing located on pier 3. Repair cracks in concrete on pier tops to prevent further break down from vegative growth.



111 Willow Street Colfax, WI 54730 (715) 962-2800 FAX: (715) 962-2801

# **PROPOSAL**

March 27, 2024

To: Oconto County Snowmobile Trail Administrator

Re: Railroad Retrofit Snowmobile Bridge Budget

## 532' x 12' (clear width) steel bridge railroad retrofit

Design Standards: Wisconsin DNR

Clear width: Inside face structural elements at deck level

End Vertical: Square

• Bearings: Equal Elevations

Steel Grade: A588/A847 (Self-Weathering)
 Deck: #1 Southern Yellow Pine (Treated)

Safety Rails: Horizontal (4" opening)

Installation: Included with removal of existing deck and railroad ties

• Loads: 85 psf live load - 35 psf wind load - 25,000 lbs. vehicle load

FOB: Oconto County, WI

Engineered Drawings State Seal: Wisconsin

Price ------\$800,000

 Structure (Steel Frame) Included Structure Engineering Included Site Prep Included **Demolition** Included Disposal Included Labor Included **Not Included** Rip Rap **Substructure Evaluation** Not Included

\*\*\*\*\*\*This price is for budgetary purposes only\*\*\*\*\*\*

Please call with any questions.

Thank you,


Kory S. Weathers

Guidelines for Applicant

Complete this form for each bridge structure you are submitting a grant application for. Provide any additional documents not requested on application checklist to substantiate your points, including actual deeded easements. Possible

requested on application checklist to substantiate your points, including actual deeded easements.	Possible	Actual
Category	Points	Points
1 Condition of the Structure (max of 10 points)		
Has a certified bridge inspection report that supports the project & demonstrates need (see	10	10
example, must provide copy of report by August 1 for 2024 only)	10	
2 Permits (maximum points 4)		and the second
Consultation with DNR Water Mgmt Specialist has occurred & permit is likely, if needed	1	
Permit in hand / Bridge already permitted - No Permit Weded	3	
3 Funding (maximum points 2) Are other funds already committed?		
50% or greater from other funding source(s)?	2	2
11% - 49% from other funding source(s)?	1	
4 Length of Written Easements or Land Use Agreement (max points 5)(ch.		22.00.22.10
23,09(26)(am)1 WI Stats)		
On public land (County, State, Federal)	5	_5_
10 or more year deeded easement on private land or other public land, for all portions of	. 5	
that trail to the nearest road on each side of the bridge		
3-9 year deeded easement on private land or other public land, for all portions of that	4	
trail to the nearest road on each side of the bridge	<del></del>	-
10 or more year deeded easement on private land or other public land, for just the bridge	3	ı I
site  3-9 deeded easement on private land or other public land, for just the bridge site	2	
10 or more year land use agreement (LUA, not deeded) on private land or other public	1	<u></u>
land	1	
3-9 year land use agreement (LUA, not deeded) on private land or other public land	0	
5 Miles Impacted – How many miles will need to rerouted if the structure is not replaced?	77777600	
Measured from nearest intersection on both sides of the bridge. (max 4 points)		
3 (		
Less than 20 miles	1	-1
20 miles or more	3	
No other snowmobile trails connect. Explain:	4	
DEDUCTIONS		
6 County Active Project Deduction (maximum deduction 1 point) A snowmobile active		
project is one that has exceeded it's initial grant period.		
	1	
Two or more active projects - deduct 1 point	-1	
GRAND TOTAL	:	* <b>८</b> (

Comments/Notes:



# **Bridge 23 Aerial Map** Bridge 23

0.5 Miles



Intermittent Streams

Lakes and Open water

Rivers and Streams

Notes

NAD\_1983\_HARN\_Wisconsin\_TM


1: 15,840


sources, and are or w
used for navigation, i
ownership or public a
applicability for a par
map. For more inform

0.5

0.25

DISCLAIMER: The information shown on these maps has been obtained from various sources, and are of varying age, reliability and resolution. These maps are not intended to be used for navigation, nor are these maps an authoritative source of information about legal land ownership or public access. No warranty, expressed or implied, is made regarding accuracy, applicability for a particular use, completeness, or legality of the information depicted on this map. For more information, see the DNR Legal Notices web page: http://dnr.wi.gov/legal/





NAD\_1983\_HARN\_Wisconsin\_TM

1: 15,840

Legend Lake Class Areas Riverine/ditch Class Areas Wetland Class Areas Wetland Class Points Dammed pond Excavated pond Filled/drained wetland Wetland too small to delineate Filled excavated pond Filled Points Wetland Class Areas Filled Areas Lake Class Areas Riverine/ditch Class Areas Wetland Class Areas Wetland Class Points Dammed pond Excavated pond Filled/drained wetland Wetland too small to delineate Filled excavated pond Filled Points Wetland Class Areas Filled Areas Wetland Identifications and

Confirmations

Municipality

State Boundaries

County Boundaries

Major Roads

Interstate Highway

State Highway

US Highway

US Highway

County and Local Roads

County HMV

Notes

applicability for a particular use, completeness, or legality of the information depicted on this map. For more information, see the DNR Legal Notices web page: http://dnr.wi.gov/legal/

# **Inspection Report for**

# **Structure 23**

# Oconto Co. Rec. Trail over Oconto River November 20, 2020



	Inspection Type	Prior	Team Leader	Frequency	Performed						
	Routine	n/a		24 mo.							
Latitude	44.870595		Owner								
Longitude	-88.275328		Maintainer								
	Hours Minutes Team Members										
Time Log		Kri	is Olson, Brian Epley								
Weather											
	Name	Nur	mber Signature		Signature Date						
Inspector	Brian Epley	97	12 Brian e	Epley	5/7/2021						

# **BRIDGE INSPECTION REPORT**

Wisconsin Dept. of Transportation
DT2007 7/2003 (Replaces DT1544) s.84.17 Wis. Stats.

Inventory Data																	
Feature On: Occ	N	Maintainer: Oconto Co. Forest & Parks Dept.							Structure Number: 23								
Feature Under: (	Oconto Riv	/er			5	Sect/Twn/Rng: S26 T28N R18E											
Location: N. of S	Shawano I	ine Ro	l., W. of Ne	lson l	Rd C	County: Oconto					Municipality:	Town	of Gillett				
Inv Rating: n/a		Rdw	y Width: 1	0'		Deck Width	h: 10'	,			Existing Posti	ng: n	/a				
Oper Rating: n/a	a	Tota	l Length: 5	532		Deck Area:	: 5320	) sf			ADT On:	Yr	: <i>F</i>	DT Under:		Yr:	
Inspection Type (	* = Addi	tional .	Applicable	e For	m(s) Red	quired)											
	Routine	outine Visual Fracture Critical*			cal* I	In-Depth*			JW-Dive* UW-Surv.		UW-Surv.*	UW-Probe/ Visual*		Мо	Movable*		
Last Insp.																	
Frequency																	
Recom. Freq.	24 mo.																
	Initia	al*	Dan	nage		Interim		Loa	ad Posted	d Posted		SI 8	SI & A Field Review*				
Last Insp.																	
Frequency	N/A	4															
Recom. Freq.	N/A	4									Item No. Nee	ding C	Change				
Load Rating Info	ormation																
Overburden	File Mea	ıs. (in):		File	Insp. Dat				/leas. (in)	:		Туре	<b>e</b> :				
Section Loss	File Mea	ıs. (%):		File	Insp. Dat	Date: Insp. Meas.				):		Desc	cribe:				
Should structure b	e re-rated	for loa	ad carrying	capa	city? (Y/N	(N) Reason:					Date	last rated:					
Clearances (Card	inal = N oı	rE)		ſ		File Meas. (ft.)					File Date Ne				w Meas. (ft.)		
Min. Vertical Clea			rdinal)				· /										
Min. Vertical Clea	rance Unc	ler (No	n-Cardinal)														
Min. Vertical Clea			,														
Structure Type				!					Constri	ıction	/Rehabilitatio	n Hist	orv				
Material			Configurati	on		# of Overall Spans Length			Year		Work F		•	Plar	ı	Shop	
Steel	Dec	k girde				6	528'		1917	Bui	lt .						
Olcci	DCC	k girac	<i>-</i> 1			0	320		1317	Dui	ii.						
	ı					ı	1										
Inspection Infor	mation							ı									
Special Requirem		Y/N			Comme	nts											
Traffic Control																	
Access Equipmen	ıt																

Other


ent Inspec	ction (x) C	heck Elements Inspected			Q	uantity in Co	ondition Sta	ates					
Elem.	Def.	Description	Unit	Total	1	2	3	4					
31		Timber Deck	SF	5320	5320								
Comments:	unable	to inspect bottom of deck, floor beams are tight	together			•							
510		Wearing Surfaces (Other)	SF	5320	5142	127	51						
Comments:													
	8912	Deterioration/Distortion – Wearing Surface				127	51						
Comments:													
107		Steel Open Girder/Beam	LF	1056		1056							
Comments: 2 girders, built up sections with plates, angles, cover plates, and stiffeners. All connections are riveted.													
	1000	Corrosion				1056							
Comments:	Freckle	d rust throughout, but no section loss was noted				•		1					
8516		Painted Steel	SF	31680				3168					
Comments:								•					
	3440	Effectiveness	SF					3168					
Comments:	The ma	ijority of the steel is unprotected, what appears t	o be left of	the paint is large	ely ineffective								
210		Reinforced Concrete Pier Wall	LF	25		25							
Comments:	Pier 5 -	Square											
	1130	Cracking (RC)/ Efflorescence				25							
Comments:	Minor	miscellaneous cracking throughout, some light to	moderate e	efflorescence.				•					
213		Masonry Pier Wall	LF	108		108							
Comments:	Piers 1	& 4 - Square - 25', Piers 2 & 3 - Skewed - 29'				•		1					
		I				108							
	1610	Mortar Breakdown											
Comments:	There a	Mortar Breakdown  are minor issues with joints breaking down and vier filling gaps.	egitation gro	owing our of gap	s, mainly in th	e caps. Vegeta	tion must be i	removed.					
Comments:	There a	re minor issues with joints breaking down and v	egitation gro	owing our of gap	s, mainly in th	e caps. Vegeta	tion must be I	removed.					
	There a	are minor issues with joints breaking down and voer filling gaps.			s, mainly in th	1	tion must be i	removed.					
215	There a	are minor issues with joints breaking down and veer filling gaps.  Reinforced Concrete Abutment			s, mainly in th	1	tion must be	removed.					
215	There a Consider	Reinforced Concrete Abutment - 20', N. Abut. 18'  Cracking (RC)/ Efflorescence miscellaneous cracking throughout, some light to	LF	38		38							

	Comments:	2 Bearir	ngs at each pier										
		1000	Corrosion				10						
	Comments:	The bea	arings have light freckled rust that does not app	pear to affect t	:he operation of	the bearings.							
	313		Fixed Bearing	EA	14		13	1					
	Comments:	2 Bearin	ngs at each abutment and each pier										
		1000	Corrosion				13						
	Comments:	The bea	arings have light freckled rust.										
		1020	Connection					1					
	Comments: The east bearing at pier three has a crack throught the base plate and extending up through one of the vertical sections. With the light loads experienced by the bridge, this defect is not a significant concern.												
	332		Timber Bridge Railing	LF	1064	1051	5	8					
	Comments:												
		1900	Distortion				5	8					
	Comments:			'									
	8400		Integral Wingwall	EA	4		4						
	Comments:												
		8903	Wingwall Deterioration				4						
	Comments: Minor cracking and deterioration.												
	Comments:												
	Comments:												
	Comments:												
	Comments:												
SS	sessme	ents											
			heck Elements Inspected					ndition Sta	ī				
k	Elem.	Def.	Description	Unit	Total	1	2	3	4				
	9167		Steel Diaphragm	EA	55		55						

	Comments	;:											
	<u> </u>	_							<del></del>	<u> </u>	1	T	<del>1</del>
	9169			Lateral I	Bracing			EA	6		6		
	Comments	, <b>:</b>	1 for ea	ch span									
	<u> </u>								<del></del>		<del></del>	<del></del>	<del></del>
	<u> </u>			Щ.						<u> </u>			
	Comments	:											
	├──								Т	<del></del>	Т	T	T
	0			<u></u>				<u></u>					
	Comments	:											
	<del> </del>			$\overline{}$				$\overline{}$	Т	$\overline{}$	1	1	T
	Comments	<u></u>		<u> </u>				<u></u>					
		•											
										T			<u> </u>
	Comments	 3:						<u> </u>					
										1			
	Comments	j:						<u></u>			<u>.</u> l	.1	<u>,                                    </u>
	<u> </u>												
				NBI	l Rating					Maintenan	ce Recomn	nendations	
NBI			File	New	NBI	File New			Item	Cost	Comment	:S	
Deck			<u> </u>	6	Appro					<del> </del>	<u> </u>		
	erstructu		<u> </u>	6	Chann					<del> </del>			
Subs	tructure		<u> </u>	6	Water	rway	8			<u> </u>			
	_												
Ma	inten	an	ce It	ems	1								
Item						Priority	Recomme	ended by	1	St	atus	Status Change	
Misc	– Cut Br	rush	1		l	high	Eple	ev. Bria	n (9712)	ider	ntified		
							-r-						
Plant	s and tree	es gr	owing	on pier	rs need	to be removed.	. Consider	patchin	ıg/filling join	ts to preven	t future grov	wth.	
Deck	c – Repai	r Ra	ailing			medium	Eple	ey, Bria	an (9712) ide		ntified		
			::	:1:									
repia	ce broker	ı and	iissim t	ng raiiii	ng 								
Deck – Patching						medium Epley, Bria			n (9712) identified				

replace broken and missing deck boards, replace previous repairs made with plywood






Railing shows signs of age but also has several damaged or decaying locations.













Wearing surface is aging but mostly intact. Several locations need proper replacements or repairs.













Main steel plate girders









Cracked bearing at pier 3, east side


















Underside of deck



Name plate



South Abutment



North Abutment













Piers