Clear Data Print... Save...

### #15 Kewaunee Krok Creek Bridge

State of Wisconsin Department of Natural Resources dnr.wi.gov

Due Date: April 15

**Motorized Recreation Grant Application** 

Motorizou itooroution oran	· / ippiioatioii
For: (choose all that apply)	Form 8700-159 (R 02/2024)
☐ AT\//UT\/ Trail Aid	Page 1 of 5

**Notice:** Completion of this form is required under Wisconsin Statutes 23.09(26) and 23.33. Failure to complete this form will result in denial of financial assistance. Personally identifiable information found on this form is not intended to be used for any other purpose. The Department of

Natural Resources (DNR) may provide this in									
Instructions: Applications may combine					DNR Us	e Only			
be submitted for consideration of traditio Stewardship funding. Submit one copy o necessary attachments. Send application	ments.	See Page	2 for	Category			Number		
Section 1: Applicant Information				1,420			Fuel		
Applicant / Organization Name				Check Rec	ipient: I	ndividual other tha	an autho	rized in	dividual to act
Kewaunee County			C	on behalf o	f the ap	plicant. 🖂 S	elect if th	ne sam	e as applicant.
Individual Authorized to Act on Behalf of	Applicant	per Resolut	tion (	Check Red	cipient	Name (Name to A	Appear o	n Ched	ck)
Dave Myers									
Title			ī	Title					
Promotions & Recreation Director									
Address			A	Address					
E4280 County Road F									
City	State	ZIP Code	, (	City		á.		State	ZIP Code
Kewaunee	WI	54216	6						
Telephone Number	Email	Address							
920-388-0444	myers	.david@k	ewaur	neeco.org					
Section 2: Project Information Requi	red for al	l Projects	1 1		100	TO SEE STATE			
Project Title				ł	Current	t Funded Miles	New M	liles (if	applicable)
Kewaunee County Bridge Rehab 2024-2025									
County	ship Rang	ge OE S	ection	1/4 1/4	1/4	GPS Coordinate	es:		
Kewaunee	N	Ow		-	-	Long.			
Project Description Summary									

Kewaunee County proposes to demolish and remove the failing bridge over Krok Creek and replace it with an engineered structure that is larger and has the necessary weight rating.

×	I certify	that	all	maintenance	land	use	agreements	are on f	ile.

<b>Estimated Cost</b>					BOME WHEELS	THE PARTY OF THE P			
Maintenance	Acquisition	Insurance	Development	Bridge Rehab.	Trail Rehab.	Total Estimated Cost			
56190				143,300					
			Leave Blank - D	NR Use Only					
Applicant Certif	ication								
Printed Name of Authorized Official				Official's Title					
Dave Myers				Promotions & Recreation Director					

As the applicant's authorized official, I certify that, to the best of my knowledge, the information in this application is true and correct.

Daile	4/12/24
Signature Authorized Official	Date Prepared

#### **Motorized Recreation Grant Application**

Form 8700-159 (R 02/2024)

Page 3 of 5

Appendix A – Required for Bridge Rehab/Replace	e, New, or Reroute with New B	ridge				
⊠ Bridge Rehab/Replace ☐ New Bridge ☐	Reroute with new bridge					
	ction 1/4 1/4 GPS Coordinate					
I N OW	NW NE Lat. 44.443	928				
Water Body Name	Bridge Name	County Inventory Number				
Krok Creek	Kewaunee-20	20				
Funded Trail Name or Number (SNARS if applicable)	Has this bridge site ever received deve	• 10 min 1 m				
KF-KR	in the past? Yes No Ye	ear:\$				
Bridge is located on: Private property	Old Bridge/Culvert Size 72.5x10					
Public property	New Bridge/Culvert Size 70x12					
Landowner Where Bridge is Located	Telephone Number Length of T	rail Use Agreement (5 year minimum)				
Wisconsin DOT	NA NA	minimum				
Current maximum load 15000 lbs. Age of Brid	lge Bridge Material					
Proposed maximum load 25000 lbs. 19 years	s wood					
Sponsoring Club Name	lub Contact	Telephone Number				
Kewaunee Moonriders	oby Cherovsky	920-660-2531				
	What is the maximum load of the other bridges on the system if					
○ Yes • No gi	coomed with this bridge?					
What is the weight of your puller & drag/grading equipment?						
14000 lbs						
What other recreational trail uses are planned for this bridge?						
None						
If there are other Recreational uses planned, how much of the bi	ridge cost will be paid for by non-snowm	obile or non-ATV users?				
Yes	anagement Specialist (WMS) regarding	a permit?				
● Yes   ○ No Is a permit needed? (Please provide any write	ten correspondence from WMS.)					
● Yes  ○ No Have you contacted your County Zoning Dept	. regarding a floodplain determination?					
● Yes  ○ No Will an H & H (hydrologic and hydraulic) stud	y be required?					

#### **Bridge Project Detailed Description**

After inspection, bridge #20 on trail section KF-KR in Kewaunee County has been reccomended for future replacement (Inspection paperwork is attached.) If approved, Kewaunee County will begin the process of applying for the required permits for this project including wetlands/delineation, H&H, waterways, DOT right of way permitting and any other required information. Currently the trail runs parallel to Highway 29 between Church and St. Peters Road and is approximately 40' or more from the roadway within the Department of Transportaion Right of Way. If the bridge was closed the reroute would be approximately 8 miles away from the crossing dependent on direction of travel. Total cost of the project is estimated around 143,300.

### **Motorized Recreation Grant Application**

Form 8700-159 (R 02/2024)

Page 4 of 5

	Bridge Structure	
	Quote 1	Quote 2
	<ul><li>Steel</li></ul>	<ul><li>Steel</li></ul>
Bridge Dimensions:	70x12	100x12
Bridge Manufacturer: Custom	V. (C.) (MARKATON AND AND AND AND AND AND AND AND AND AN	Wheeler
Design Weight Load	25000 lbs.	
Cost of Structure: 1. Engineering	\$ 3000	\$
2. Structure	\$ 102600	\$ <u>150000</u>
Subtotal	\$	\$
	Quote 1	Quote 2
•	) Contractor or O Sponsor	<ul><li>Contractor or O Sponso</li></ul>
nstallation Costs:	Estimate	Estimate
1. Engineering	\$	\$
2. Site Preparation	\$ 13300	\$
3. Abutments	\$	\$
4. Pilings/Piers	\$	\$
5. Approaches	\$	\$
6. Riprap	\$	\$
7. Labor	\$	\$
8. Equipment Rental	\$ 4400	\$
9. Culverts	\$	\$
10. H & H Study	\$	\$
11. Wetland Delineation	\$	\$
12. Other <u>permitting</u> inspection	\$ 20000	\$ 20000
Subtota	al \$	\$
Total Cos	st \$ 143,300	\$ 170,000
For the application grant, yo	u must take the lowes	st of the two quotes.
Entire Deck and Railing Projects	<ul><li>Contracto</li></ul>	r O Sponsor O Club
Bridge Dimensions:		
Design Weight Load	lbs.	
1. Materials	\$	
2. Labor	\$	
Tota	1 \$	



## Custom Manufacturing, Inc.

606 Delco Drive, P.O. Box 279

Clinton, WI 53525 608-676-2282 Fax: 608-676-2283

tina@custommfginc.com



Please Indicate The Above Number When Ordering

Date: April 5, 2024	Salesperson: Tina Forrest
Inquiry Date:	Inquiry Number

To: Kewaunee County
Promotions & Recreation
E4280 County Road F
Kewaunee, WI 54216

Estimated Ship Date 8 – 12 weeks		Shipped VIA Best Way	Terms Net 30		
		Desci	Price	Total	
	2	2024 GRANT APPLI	E		
1	Do	uble Decked - 42" H	Wide - 25,000# Load orizontal Railing — Galvanized Sill Pans	\$ 102,600.00	
	Inst Equ	mped Engineered Dra callation & Site Prepa sipment Rental ivery Charges	awings aration (Gravel/Rip Ra	3,000.00 13,300.00 3,200.00 1,200.00	
			Total		\$ 123,300.0
	1	above prices do not essary permits.	include sales tax or ar	ny	
	Cro red Pine		e predrilled and have MCA Southern Yellov all hardware.		
	500.8775	dge Kit Meets - WI D 000# Load	NR Guidelines –		

We are pleased to submit the above quotation for your consideration. Should you place an order, be assured it will receive our prompt attention. This quotation is valid for 30 days. Thereafter it is subject to change without notice.


Tina Forrest		
BY:	ACCEPTED:	DATE:

### **Guidelines for Applicant**

Complete this form for each bridge structure you are submitting a grant application for. Provide any additional documents not requested on application checklist to substantiate your points, including actual deeded easements.

Category	Possible Points	Actual Points
1 Condition of the Structure (max of 10 points)	MARKET KIND	Harris Laborato
Has a certified bridge inspection report that supports the project & demonstrates need (see	10	10
example, must provide copy of report by August 1 for 2024 only)	10	, 0
2 Permits (maximum points 4)		
Consultation with DNR Water Mgmt Specialist has occurred & permit is likely, if needed	1	0
Permit in hand / Bridge already permitted	3	0
3 Funding (maximum points 2) Are other funds already committed?		
50% or greater from other funding source(s)?	2	0
11% - 49% from other funding source(s)?	1	0
4 Length of Written Easements or Land Use Agreement (max points 5)(ch.	a la	
23.09(26)(am)1 WI Stats)		
On public land (County, State, Federal)	5	<b>9</b> 5
10 or more year <b>deeded easement</b> on private land or other public land, for all portions of	5	6
that trail to the nearest road on each side of the bridge		
3-9 year <b>deeded easement</b> on private land or other public land, for <u>all portions of that</u>	4	0
trail to the nearest road on each side of the bridge		
10 or more year <b>deeded easement</b> on private land or other public land, for just the bridge	3	0
site	2	0
3-9 <b>deeded easement</b> on private land or other public land, for just the bridge site 10 or more year land use agreement (LUA, not deeded) on private land or other public	1	
land	' 1	0
3-9 year land use agreement (LUA, not deeded) on private land or other public land	0	0
5 Miles Impacted – How many miles will need to rerouted if the structure is not replaced?	(A)	
Measured from nearest intersection on both sides of the bridge. (max 4 points)	OFF RESEARCH	0E(0) & 1) & 010
readiled from fleatest intersection on ooth states of the orage. (mail i points)		
Less than 20 miles	1	
20 miles or more	. 3	0
No other snowmobile trails connect. Explain:	4	0
DEDUCTIONS		
6 County Active Project Deduction (maximum deduction 1 point) A snowmobile active		
project is one that has exceeded it's initial grant period.		
Two or more active projects - deduct 1 point	-1	0
GRAND TOTAL		16

Comments/Notes:






#### **Kewaunee County GIS**

Kewaunee Bridge #20 Trail Section KF-KR






Kewaunee County Land Information Office 810 Lincoln St Kewaunee, WI 54216 920-388-7190



### **Kewaunee County GIS**

Kewaunee Bridge #20 Trail Section KF-KR







SCALE: 1" = 99 '



Kewaunee County Land Information Office 810 Lincoln St Kewaunee, WI 54216 920-388-7190





### Kewaunee County GIS Snowmobile Bridge

DISCLAIMER: Kewaunee County does not guarantee the accuracy of the material contained here in and is not responsible for any misuse or misrepresentation of this information or its derivatives.

SCALE: 1" = 101 '





Kewaunee County Land Information Office 810 Lincoln St Kewaunee, WI 54216 920-388-7190

Print Date:

3/26/2024





West Approach Looking East



North Profile




Upstream Channel




Downstream Channel



Typical Wearing Surface of Main Span



West Approach Span – Overview of Rotten Deck Boards



Typical Vegetation Growth in between Deck Boards



Gap Between Approach Span and Main Span (West Shown)



Main Span – Wearing Deck Board Removed Showing Minor to Moderate Rotten Transverse Boards



Typical Surface Rot of Transverse Deck Boards



Main Span – Wearing Deck Board Removed Showing Minor to Moderate Rotten Transverse Boards



Typical Surface Rot of Transverse Deck Boards



Typical Deterioration of the Transverse Deck Board Ends



Sag in Main Span



2.5 Inch Sag over 4 Feet



South Fascia Timber Girder (Pole) with Minor Splinter and Section Loss



South Fascia Timber Girder (Pole) with Minor Splinter and Section Loss



Typical Checks and Surface Rot of Timber Girders (Poles).



Typical Timber Pier on Channel Banks (Southwest Quadrant Shown)



West Bank Timber Pier Log with 100% Section Loss of the Center with 14 inches of Penetration



West Bank Timber Pier Log with Moderate Surface Rot and Deterioration



Southeast Quadrant with no Support of the Main Span



Loose and Missing Timber Supports in the Southeast Quadrant

### **BRIDGE INSPECTION REPORT**

Wisconsin Dept. of Transportation
DT2007 7/2003 (Replaces DT1544) s.84.17 Wis. Stats.

Inventory Data											-14				
Feature On: Snowmobile Trail Along STH 29					Maintainer: Kewaunee County Parks – Promotion & Recreation					Structure Number: STH 29 – Snowmobile Bridge					
Feature Under: Krok Creek					Sect/T	wn/Rng	:								
Location: 44.4433	37, -87.62	928			County: Kewaunee					Municipality: Town of Wes				st Kewaunee	
Inv Rating: -		Rdw	y Width: 1	0'	Deck V	Vidth:	10'			Existing	Postir	ng: -			
Oper Rating: -		Tota	I Length:	72.5'	Deck A	Area:	725	SF		ADT On	: -	Yr: - A	DT Und	er: - \	/r: -
Inspection Type	( * = Ad	ditiona	ıl Applicabl	e Form(	s) Require	ed)									
	Routine	Visual	Fracture	Critical*	In-Dep	oth*		UW-Dive*		UW-Su	rv.*	UW-Prob Visual*		Mova	able*
Last Insp.			-		-			-		-		_		-	
Frequency			-		1/2					121		_		-	
Recom. Freq.	12 Mo	nths	-		-			-		-		-		-	
	Initia	al*	Dam	age	Interi	m	L	oad Posted	1			SI & A Field	d Review	v*	
Last Insp.	4/5/2		-	i)	-			-				-			
Frequency	N/A		-		-							-			
Recom. Freq.	N/A	Α	-		-					Item No.	Need	ing Change			
Load Rating Info	ormation														5
Overburden	File Mea	as. (in):	-	File Insp	. Date: -			Meas. (in):				Type: -			
Section Loss	File Mea				. Date: -		-	Meas. (%)				Describe: -			
Should structure b	e re-rated	d for loa	ad carrying o	apacity?	(Y/N) N		Reas	ion: -				Date last rat	ed: -		
Expansion Joint	s			Temp.		T	Si	gning Con	dition						
100 To all				File	File	New				1	Υ				
Location		Тур	)e	Insp. Date	Insp. (in.)	Insp. (in.)	$\perp$	Type of Ma		File	N N/A	Comments			
						1	_	idge Marke		1					
NO 10 10 10 10 10 10 10 10 10 10 10 10 10							_	rrow Bridge							
							_	ne Lane Ro							
						1	_	rtical Clear	ance	-		+			
					-		_	eight Limit	ian)	+		+			
						1	Tot	her(Addl. S	ign)						
Clearances (Cardi			HEOD - DOWN		File M		File Date				New I	Meas. (ft.)	)		
Min. Vertical Clear													<del>7. 17.</del>		
Min. Vertical Clear		der (No	n-Cardinal)												
Min. Vertical Clear	ance On														
Structure Type								Constru	ction/F	Rehabili	tation	History	-		,
Material		Co	nfiguration		# of Ove Spans Lengt		-	Year		Work Performed				Plan	Shop
Timber		Deck	with Girder	s	3	72.									
Inspection Inform	nation									100					
Special Requireme		Y/N		Cor	nments										
Traffic Control															
Access Equipment	t	Υ	Waders			100.00	310								
Other															
Inspector Inform	ation														L
Team Leader Nam Cory L. Thomson	ne and No	. Printe	ed:/ //	Tea	ım Membei	(s) Nan	ne(s) F	Printed:							
Team Leader Sign	ature:	(	LL				Ins	p. Date: 4/	5/2024			Agency: TANT (10)			
District/Local Manager and No. Printed:				Dist	trict/Local N	/lanager	Signa	ature:					Revie	w Date:	

Rement Inspection (X) Check Elements Inspected  Relement Defect Description Unit Total QTY  31 Timber Deck SF 725  Comments: All approach deck boards have minor to moderate checks and wear damage down the to ¼-inch surface rot. The west approach span has two deck boards that are in severe condition will The east approach span has one deck board that is completely split and another one that is severel boards in both approach spans are in CS2.  The main span has longitudinal timber wearing boards and transverse timber deck boards. The west surface rot up to ¼ inch and a few loose boards. The boards are loose because the surface of the total fasteners don't hold. Two of the longitudinal wearing boards were removed to inspect the transvers have surface rot up to ½ inch deep and random boards with up to 10% section loss. The ends of the are severely weathered. The main span is in CS3 because of the condition of the transverse deck to the timber curb/fascia board in the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and no longer attached at the joint the southwest quadrant is broken and	aring boards are transverse deck the deck boards. the transverse bo	304 poards are westion loss (C 24 SF). The	22 eathered with cS4 = 22 SF). e rest of the de
Comments: All approach deck boards have minor to moderate checks and wear damage down the to ¼-inch surface rot. The west approach span has two deck boards that are in severe condition will The east approach span has one deck board that is completely split and another one that is severel boards in both approach spans are in CS2.  The main span has longitudinal timber wearing boards and transverse timber deck boards. The west surface rot up to ¼ inch and a few loose boards. The boards are loose because the surface of the transverse don't hold. Two of the longitudinal wearing boards were removed to inspect the transverse have surface rot up to ½ inch deep and random boards with up to 10% section loss. The ends of the are severely weathered. The main span is in CS3 because of the condition of the transverse deck because the surface of the transverse deck because the surface of the transverse deck because the surface of the transverse deck because of the condition of the transverse deck because the surface of the transverse deck because the surf	399  center. Deck bith up to 30% sely rotten (CS3 –  aring boards are transverse deck be deck boards. The transverse boards.	304 poards are westion loss (C 24 SF). The heavily wear boards are	22 eathered with cS4 = 22 SF). e rest of the de
Comments: All approach deck boards have minor to moderate checks and wear damage down the to ¼-inch surface rot. The west approach span has two deck boards that are in severe condition wind The east approach span has one deck board that is completely split and another one that is severel boards in both approach spans are in CS2.  The main span has longitudinal timber wearing boards and transverse timber deck boards. The weat surface rot up to ¼ inch and a few loose boards. The boards are loose because the surface of the transverse don't hold. Two of the longitudinal wearing boards were removed to inspect the transvershave surface rot up to ½ inch deep and random boards with up to 10% section loss. The ends of the are severely weathered. The main span is in CS3 because of the condition of the transverse deck because the surface rot up to ½ inch deep and random boards with up to 10% section loss.	center. Deck bith up to 30% sely rotten (CS3 – aring boards are transverse deck be deck boards. be transverse bo	poards are we cotion loss (C 24 SF). The e heavily wear boards are	eathered with CS4 = 22 SF). e rest of the deathered with
to ¼-inch surface rot. The west approach span has two deck boards that are in severe condition will The east approach span has one deck board that is completely split and another one that is severel boards in both approach spans are in CS2.  The main span has longitudinal timber wearing boards and transverse timber deck boards. The west surface rot up to ¼ inch and a few loose boards. The boards are loose because the surface of the transverse have surface rot up to ½ inch deep and random boards with up to 10% section loss. The ends of the are severely weathered. The main span is in CS3 because of the condition of the transverse deck because the surface rot up to ½ inch deep and random boards with up to 10% section loss. The ends of the are severely weathered. The main span is in CS3 because of the condition of the transverse deck because the surface rot up to ½ inch deep and random boards with up to 10% section loss. The ends of the are severely weathered.	aring boards are transverse deck the deck boards. the transverse bo	ection loss (C 24 SF). The heavily wea boards are	CS4 = 22 SF). e rest of the de
span.  The entire main span moves up and down approximately 2 inches when a person bounces on the do		ards have w - pproach spa	erse deck boar ide checks an an and main
support for the main span deck in the southeast quadrant.  111 Timber Girder (Pole) LF 358	134	224	T
Comments: There are 3 timber poles that support the timber deck in the west and east approaches.			hat curport th
Comments: The ends of the main span at the edge of the banks are supported by a timber pier that and logs. The approach spans are also supported by this built-up timber pier. The beginning of each ground with no visible supports.  The log support of the west bank timber pier has moderate to heavy rot and deterioration. The north center of the log that is 6-inch diameter and with 14 inches of penetration. The outer portion of the low with minor section loss up to ¼ inch. The log support is also split and has end shakes (CS3 – 12 LF).	ch approach spa n end of the log og support also	ans rest direct	otly on the
The timber pier of the east bank is in serious condition. The supports in the southeast quadrant are timber girders and deck. The entire main span moves up and down approximately 2 inches when a pecause there is no support for the main span deck in the southeast quadrant (CS4 – 12 LF).			
		-	
paral Inspection/Mointenance Notes			
ucture is orientated/inventoried from west to east. annel banks are heavily vegetated and appear to be stable. Minor to moderate vegetation and brush in	channel downst	tream of brid	ge.
ucture is orientated/inventoried from west to east. annel banks are heavily vegetated and appear to be stable. Minor to moderate vegetation and brush in a STH 29 bridge is just upstream of the snowmobile bridge.		tream of brid	ge.
			ge.
ructure is orientated/inventoried from west to east.  Iannel banks are heavily vegetated and appear to be stable. Minor to moderate vegetation and brush in e STH 29 bridge is just upstream of the snowmobile bridge.  Ispection completed during high flows. The water depth in the main channel was approximately 4 to 5 fee NBI Ratings  Maintenance  I File New NBI File New Item Priority Commer	et deep. Recommendati	ons	

		NBI Ra	tings		
NBI	File	New	NBI	File	New
Deck		4	Culvert		NA
Superstructure		5	Channel		9
Substructure		2	Waterway		8

Item	Priority	Comments			
Long term recommendation	High	Begin planning and schedule structure for replacement.			
212 – Timber Pier Wall	High	Short term recommendation. Replace the missing timber supports in the southeast quadrant to support the main span girders and deck.			
31 – Timber Deck High		Remove and replace the rotten and deteriorated approach deck boards.			
31 – Timber Deck	High	Remove and replace the timber curb/fascia in the southwest quadrant.			
31 – Timber Deck	Low	Remove and replace the transverse and wearing surface deck boards of the main span.			