

S-21 Tri Co/Cheese Country Bridge #28

State of Wisconsin
 Department of Natural Resources
dnr.wi.gov

Motorized Recreation Grant Application

For: (choose all that apply) Form 8700-159 (R 02/2024)

Due Date: April 15

- ATV/UTV Trail Aid
- Snowmobile Trail Aid

Notice: Completion of this form is required under Wisconsin Statutes 23.09(26) and 23.33. Failure to complete this form will result in denial of financial assistance. Personally identifiable information found on this form is not intended to be used for any other purpose. The Department of Natural Resources (DNR) may provide this information to requesters as required by Wisconsin's Public Records law (ss. 19.31 – 19.39, Wis. Stats.).

Instructions: Applications may combine more than one source of funds. They may be submitted for consideration of traditional ATV, UTV, Snowmobile and Motorized Stewardship funding. Submit one copy of all forms and attachments. See Page 2 for necessary attachments. Send applications to your [Community Services Specialist](#).

DNR Use Only	
Category	Number

Section 1: Applicant Information

Applicant / Organization Name Tri-County Trail Commission			Check Recipient: Individual other than authorized individual to act on behalf of the applicant. <input checked="" type="checkbox"/> Select if the same as applicant.		
Individual Authorized to Act on Behalf of Applicant per Resolution Max Blackburn			Check Recipient Name (Name to Appear on Check) Max Blackburn		
Title Tri-County Trail Coordinator			Title Tri-County Trail Coordinator		
Address 700 Main Street			Address 700 Main Street		
City Darlington	State WI	ZIP Code 53530	City Darlington	State WI	ZIP Code 53530
Telephone Number (608) 776-4893		Email Address trails@lafayettecountywi.org			

Section 2: Project Information Required for all Projects

Project Title Cheese Country Trail Bridge #28 Replacement					Current Funded Miles	New Miles (if applicable)
County Lafayette	Township 01 N	Range 4	Section 2	¼ ¼ UN	¼ UN	GPS Coordinates: Lat. 42.588625 Long. -89.990923

Project Description Summary

Proposed project is the complete replacement of Bridge #28 on the Cheese Country Trail over the unnamed stream in Lafayette County. Project scope is to include removing deteriorated components and replacement with a new structure.

During a routine bridge inspection, major deficiencies were found in the bridge structure indicating that it is at the end of its useful life (1 to 2 years of longevity left)

Currently here is the breakdown of the request from all grant programs:

ATV/UTV = \$159,676.50 (50%)
 Snowmobile = \$159,676.50 (50%)

I certify that all maintenance land use agreements are on file.

Estimated Cost

Maintenance	Acquisition	Insurance	Development	Bridge Rehab.	Trail Rehab.	Total Estimated Cost
				\$319,353.00		\$319,353.00

Leave Blank – DNR Use Only

Applicant Certification

Printed Name of Authorized Official Max Blackburn	Official's Title Tri-County Trail Coordinator
--	--

As the applicant's authorized official, I certify that, to the best of my knowledge, the information in this application is true and correct.

Max Blackburn
 Signature of Authorized Official

4-15-26
 Date Prepared

Appendix A (continued)

Summarize Costs in Appropriate Categories:

Bridge Structure

	Quote 1	Quote 2
	<input checked="" type="radio"/> Steel <input type="radio"/> Wooden	<input type="radio"/> Steel <input type="radio"/> Wooden
Bridge Dimensions:	12' X 82'	_____
Bridge Manufacturer:	TBD	_____
Design Weight Load	25,000 lbs.	_____ lbs.
Cost of Structure:		
1. Engineering	\$ 38,597	\$ _____
2. Structure	\$ 227,040	\$ _____
Subtotal	\$ 265,637	\$ _____


	Quote 1	Quote 2
	<input checked="" type="radio"/> Contractor or <input type="radio"/> Sponsor Estimate	<input type="radio"/> Contractor or <input type="radio"/> Sponsor Estimate
Installation Costs:		
1. Engineering	\$ 34,216	\$ _____
2. Site Preparation	\$ _____	\$ _____
3. Abutments	\$ _____	\$ _____
4. Pilings/Piers	\$ _____	\$ _____
5. Approaches	\$ _____	\$ _____
6. Riprap	\$ _____	\$ _____
7. Labor	\$ _____	\$ _____
8. Equipment Rental	\$ _____	\$ _____
9. Culverts	\$ _____	\$ _____
10. H & H Study	\$ _____	\$ _____
11. Wetland Delineation	\$ _____	\$ _____
12. Other <u>Soil Borings</u>	\$ 19,500	\$ _____
Subtotal	\$ 53,716	\$ _____
Total Cost	\$ 319,353	\$ _____

Included construction labor too. See attached cost estimate.

For the application grant, you must take the lowest of the two quotes.

Entire Deck and Railing Projects Contractor Sponsor Club

Bridge Dimensions:	_____
Design Weight Load	_____ lbs.
1. Materials	\$ _____
2. Labor	\$ _____
Total	\$ _____




Bridge #28

Guidelines for Applicant


Complete this form for each bridge structure you are submitting a grant application for. Provide any additional documents not requested on application checklist to substantiate your points, including actual deeded easements.

This ranking tool is used for both **Snowmobile** and **ATV/UTV Trail Aids** programs, though each program may score things differently. If you are seeking funding from BOTH programs for a dual use bridge, please score ALL questions

Category		Possible Points	Snow Points	ATV/UTV Points
1	Condition of the Structure (max of 10 points)			
	Has a certified bridge inspection report that supports the project & demonstrates need. Copy of report needed. Snowmobile Funded Projects	10	10	
	Calculation: 10 minus NBI Rating Score (0-9) ATV Funded Projects Use overall NBI # if provided, or an average of the components. Redecking projects should just use the deck NBI #.	10		5
2	Permits (maximum points 4)			
	Consultation with DNR Water Mgmt Specialist has occurred & permit is likely, if needed	1	—	—
	Permit in hand / Bridge already permitted	3	—	—
3	Funding (maximum points 2) Has an application been submitted for other funding			
	50% or greater from other funding source(s)? (includes 50/50 Snow/ATV projects)	2	2	2
	11% - 49% from other funding source(s)?	1	—	—
4	Length of Written Easements or Land Use Agreement (max points 5)(ch. 23.09(26)(am)1 WI Stats)			
	On public land (County, State, Federal)	5	5	5
	10 or more year deeded easement on private land or other public land, for all portions of that trail to the nearest road on each side of the bridge	5	—	—
	3-9 year deeded easement on private land or other public land, for all portions of that trail to the nearest road on each side of the bridge	4	—	—
	10 or more year deeded easement on private land or other public land, for just the bridge site	3	—	—
	3-9 deeded easement on private land or other public land, for just the bridge site	2	—	—
	10 or more year land use agreement (LUA, not deeded) on private land or other public land	1	—	—
	3-9 year land use agreement (LUA, not deeded) on private land or other public land	0	—	—
5	Miles Impacted – How many miles will need to be rerouted if the structure is not replaced? Measured from nearest intersection on both sides of the bridge. (max 4 points)			
	Less than 20 miles Snowmobile Funded Projects	1	—	
	20 miles or more Snowmobile Funded Projects	3	—	
	No other snowmobile trails connect. Snowmobile Funded Explain:	4	—	
	For ATV/UTV projects, describe the relocation (on routes? Trail?) Include sketch/map		✓	
6	If ATV/UTV, Seasons of Use (max 3 points)			
	Year-Round or Summer Only ATV/UTV Trail	3		3
	Winter Only ATV/UTV Trail	1		—
	DEDUCTIONS			
7	County Active Project Deduction (maximum deduction 1 point) A snowmobile active project is one that has exceeded its initial grant period.			
	Two or more active projects - deduct 1 point	-1	-1	
GRAND TOTAL			17	15



Trail re-route because of a potential closure of #28.




Bridge is located in the purple highlighted area. This area is within FEMA regulated floodplain.



Legend: (some map layers may not be displayed)

- Wetland Class Points**
- Wetland too small to delineate
 - Wetland Indicators
 - Rivers and Streams
 - Intermittent Streams
 - Open Water
 - Rivers and Streams
 - Intermittent Streams
 - Open Water
 - 24K Intermittent Streams
 - 24K Lakes and Open Water
 - 24K Streams and Rivers
 - Latest Leaf Off Index
 - Latest Leaf Off Imagery

Notes:



Map projection: NAD 1983 HARN Wisconsin TM
 Service Layer Credits:
 Wetland Indicators & Soils[^]: Surface Water Data Viewer Team, DNR Basic Feature VTL (WTM); Wisconsin Department of Natural Resources, GIS Section, Latest Leaf Off[^]; Surface Water: WiDNR, USGS, and other data, Wetland Inventory NWI (Dynamic): Calvin Lawrence, Dennis Weise, Nina Rihn

This map is a product generated by a DNR web mapping application.
 This map is for informational purposes only and may not have been prepared for or be suitable for legal, engineering, or surveying purposes. The user is solely responsible for verifying the accuracy of information before using for any purpose. By using this product for any purpose user agrees to be bound by all disclaimers found here: <https://dnr.wisconsin.gov/legal>.

Inspection Report for

Bridge #28

Cheese Country Trail over Tributary to Pecatonica River

**Executive Summary****Recommended Inspection Frequency:**

- 12 Months.
- *Monthly interim monitoring by local forces should be completed with supplemental inspections after any suspected overload crossing.*

Estimated Remaining Longevity:

- The remaining serviceable life of this structure can be reasonably estimated at 1 year.
- There are likely no feasible rehabilitation efforts that would extend the longevity of the structure.

Summary of Channel Conditions:

- Waterway flows through Span W3, 6 ft vertically cut banks throughout.

Summary of Structural Conditions:

- Decayed timber components throughout are susceptible to overload damage.
- **Beams showing signs of overload damage (crushing) over the west abutment.**

Maintenance/Repair Recommendations: *Refer to subsequent element descriptions for detailed component specific maintenance recommendations, if applicable.*

- **Owner Notified of CS4 Condition.**
- **Bridge should be evaluated for structural capacity and posted for load.**
- Posting for reduced load capacity may extend longevity.
- Schedule for complete replacement or closure.

Nathan W. Miller
Bridge Inspection Team Leader, Inspector Number: 9601

11.13.2025

Date

Bridge ID / Structure No. Bridge #28	Inspection Date: 11.13.2025
	Inspection TL: Nate Miller, PE
	NBI Project No: 2503501
Facility Owner/Managing Agency: Tri-County Trails Commission	Representative: Max Blackburn
Email: trails@lafayettecountywi.org	Phone: 608-776-4893

Summary of Inspection Intent, Procedures, and Limitations

- NBI Engineering Services personnel visited the above referenced structure to observe the existing conditions and collect information on behalf of The Tri-County Trail Commission. The purpose of this inspection was to determine the physical and functional condition of the bridge.
- Observations have been limited to readily available surface conditions. No destructive or invasive testing procedures, load rating, or detailed measurements have been performed as part of this inspection. NBI Engineering Services reserves the right to revise our opinions if additional evidence becomes available.
- Timber conditions were evaluated by visual inspection and acoustic sounding.
- Due to access limitations, assessment of components above 6 ft above grade was limited primarily to visual observation.
- Beams inspected from ground and deck via pole cam.
- No subsurface or underwater inspection efforts have been completed.
- The facility was open to traffic during the inspection.
- No plans or prior inspection information for the structure have been provided.

Time Log | Onsite: 1.5 Hours

Inventory Data

Feature On:	Cheese Country Trail	Feature Under:	Tributary to Pecatonica River
Lat./ Long.:	42.5885, -89.9908		
Orientation:	Traffic Direction: EB/WB	Channel Flow:	Upstream: South - Downstream: North

Structure Type

No. Spans:	5	Wearing Surface:	Concrete Deck
Deck	Cast-In-Place Concrete over Timber Cross-Ties		
Superstructure	3-Ply Timber Beams	No. Beam Lines:	2
Substructure	Abutments: Timber Pile with Timber Backwall Plank		
	Pier(s): Timber Pile Bent		

Geometric - Dimensions are approximate.

Width (O-O):	9.0'	Deck Length (O-O):	82.0'
Width (C-C):	9.0'	Span Length(s):	15.0'/16.0'/16.0'/16.0'/15.5'

Assessments

Quantity in CS

Assessment	Description	UOM	Total	1	2	3	4	Comments
9001	Drainage -Ends of Structure	EA	4		4			Well Vegetated.
9004	Drainage - Structure	EA	0					No Bridge Deck Drains.
9030	Signs - Object Markers	EA	4			4		Present at All 4 Corners. Faded/Damaged.
9035	Signs - Other	EA	2	2				"BRIDGE AHEAD".
9035	Signs - Other	EA	2		2			"15 MPH ON BRIDGE". Faded.
9041	Slope Protection -Bare	EA	2		2			Natural Earth Embankments.
9324	Approach Roadway -Gravel	EA	2		2			Minor Rutting at Wheel Lines.

Bridge ID / Structure No. Bridge #28	Inspection Date:	11.13.2025
	Inspection TL:	Nate Miller, PE
	NBI Project No:	2503501

SNBI Condition Ratings & Commentary

Deck (C.01) | 4 | Poor Condition – Deteriorating

1. Concrete slab (wearing surface) over timber crossties(deck).
2. Minor wear of concrete throughout wearing surface, most pronounced along wheel lines. Multiple unsealed moderate/wide width transverse cracks throughout concrete slab.
3. Timber crossties decayed and split at ends. Signs of decay throughout all timber components. Timber preservative treatment is no longer effective.

Maintenance/Repair Recommendations

No feasible rehabilitation options to extend longevity of component.

Railings (C.05) | 4 | Poor Condition – Stable

1. Hog panel fencing supported by dimensional timber rails with angled timber posts.
2. Initial signs of incipient decay of timber components. Timber preservative treatment appears marginally effective.
3. Widespread areas of moderate to severe damage to timber curbs and rails. Widespread areas of damaged/missing hog fencing.
4. Southwest rail post cracked/broken.

Maintenance/Repair Recommendations

Repair damaged bridge rail components.

Transition Railings (C.06) | N/A | Not Applicable

Joints (C.08) | N/A | Not Applicable

Superstructure (C.02) | 2 | Critical Condition - Deteriorating

1. (2) lines of timber beams each comprised of (3) through-bolt connected laminations.
2. Beams are decayed +/- 75% throughout with widespread prominent checking and generally appear hollow when sounded. Isolated areas of more advanced decay and signs of horizontal shear cracking.
- 3. Readily evident signs of crushing over the west abutment and Pier W1.**
4. Beams are highly susceptible to overload damage.

Maintenance/Repair Recommendations

No feasible rehabilitation options to strengthen or extend longevity of component.

Bearings (C.07) | N/A | Not Applicable

Substructure (C.03) | 3 | Serious Condition – Deteriorating

Abutments:

1. Driven timber piles, timber pile caps, and timber backwall plank.
2. Decayed timber components throughout with no readily evident signs of crushing.
3. Caps are decayed +/- 50% throughout with widespread minor checking and generally appear hollow when sounded. Isolated areas of more advanced decay and splitting at ends.
4. Piles: Exposed bearing piles are starting sound hollow with an estimated 50%-75% loss of section.

Pier(s):

1. Driven timber piles and timber pile caps.
2. Decayed timber components throughout with potential signs of initial overload distress (brooming/springy pile shells) at base of isolated piles.
3. Caps are decayed 50%-75% throughout with widespread minor checking and generally appear hollow when sounded. Isolated areas of more advanced decay and splitting at ends. Full depth vertical splitting of caps in piers W2 & W4.
4. Piles: Bearing piles sound hollow with an estimated 50%-90% loss of section.
5. Pier piles and caps are highly susceptible to overload damage.

Maintenance/Repair Recommendations

No feasible rehabilitation options to strengthen or extend longevity of component.

Bridge ID / Structure No. <p style="text-align: center;">Bridge #28</p>	Inspection Date:	11.13.2025
	Inspection TL:	Nate Miller, PE
	NBI Project No:	2503501

Channel (C.09) | 6 | Satisfactory Condition - Stable

1. Embankment Erosion: Natural earth berms at both abutments appear relatively stable. 6 ft vertically cut embankments throughout channel.
2. Drift: No significant deposits in channel.
3. Channel Change: Waterway flows through span W3. Upstream channel meandering, downstream relatively straight.
4. Adequacy of Opening: No readily visible signs of overtopping.

Maintenance/Repair Recommendations

See Channel Protection.

Channel Protection (C.10) | 6 | Satisfactory Condition - Stable

1. Vegetation: Channel is well vegetated.
2. Channel Protection: No channel armoring present-unprotected embankments adjacent to substructure units appear relatively stable.

Maintenance/Repair Recommendations

Installation of channel protection would reduce likelihood of future erosion/scour issues. Channel armoring may not be feasible, and/or recommended, given the expected longevity of the structure and current observed conditions.

Scour (C.11) | 6 | Satisfactory Condition - Stable

1. Streambed Scour: Soft/silty streambed is prone to scour. Negligible channel scour observed throughout opening. All substructure units beyond channel flow during inspection.

Maintenance/Repair Recommendations

See Channel Protection.

Bridge ID / Structure No.	Bridge #28	Inspection Date:	11/13/2025
		Inspection TL:	Nate Miller, PE
		NBI Project No:	2503501

Deck

Deck Rating: **4**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4
Wearing Surface	8514	Wearing Surface-Concrete Overlay <i>Retrofit C-I-P concrete slab over timber cross ties.</i>	6	SF	738		657	81
		WS-Crack		SF				81
		CS3: 9 transverse lines of moderate/wide width cracks across width of deck.						
		WS-Abrasion/ Wear/ Rutting or Loss of Friction		0			657	
	8911	CS2: Concrete worn to large aggregate at wheel lines. Outside edges of deck covered with crushed stone/vegetation.						
Deck	31	Deck-Timber <i>Timber Cross ties.</i>	4	SF	738		369	369
		TBR-Checks/ Shakes/ Cracks/ Splits/ Delamination		SF			369	369
		CS2: Signs of timber decay throughout.						
		CS3: Full depth splitting and/or decay at end 3ft of 50% of cross ties. Assume 25% section loss across all cross ties.						
	9004	Drainage-Structure None. No bridge deck drains.	N	EA				

Bridge Railing

Bridge Railing Rating: **4**

Bridge Railing Transition Rating: **N**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4	
Railing	332	Timber Bridge Railing <i>Hog panel fencing supported by dimensional timber rails with angled timber posts.</i>	4	LF	164		49	100	15
		TBR-Decay/ Section Loss/ Abrasion/ Wear		LF			49		
		CS2: Timber rails and posts show initial signs of incipient decay and weather checking.							
		9001 Timber Preservative Treatment		LF					
		CS3: Timber preservative treatment marginally effective.							
	7000	Damage CS3: Collision damaged timber curb rail (50-lf). Damaged/missing hog fencing (50-lf). CS4: SW Rail Post cracked/broken (15-lf).		LF			100	15	

Bridge Joints

Bridge Joints Rating: **N**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4
Joints		Joint Type <i>None. Concrete bridge deck runs continuously over length of structure.</i>	N	LF				
		Defect		LF				
		N/A						

Bridge ID / Structure No.	Bridge #28	Inspection Date:	11/13/2025
		Inspection TL:	Nate Miller, PE
		NBI Project No:	2503501

Superstructure

Superstructure Rating: **2**

Quantity in Condition State

	Element	Defect	Description	OUM	Total	Quantity in Condition State					
						1	2	3	4		
Superstructure	111		Superstructure-Timber-Open Girder/ Beam <i>2 beam lines of 3-ply timber beams.</i>	2	LF	164			147	17	
		1140	TBR-Decay/ Section Loss/ Abrasion/ Wear CS3: All beams decayed and sound hollow with an estimated 75% loss of section. CS4: Isolated areas of more advanced decay estimated 90% loss of section over piers (See Damage - 7000).		LF				74		
		1150	TBR-Checks/ Shakes/ Cracks/ Splits/ Delamination CS3: Prominent checking/horizontal shear cracking(+/- 1/4") throughout length of beams. CS4: Isolated areas of splitting/crushing. (See Damage - 7000).		LF				73		
		1020	Connection Through-bolts appear intact and functioning as intended.		LF						
		1900	Distortion Beam appear properly aligned with no readily visible signs of distortion.		LF						
		7000	Damage Beams showing signs of overload damage (crushing): CS4: Span 1 (over w. abut.): South Beam (7-lf) / North Beam (5-lf). Span 2 (over pier W1): East Beam (5-lf).		LF					17	
			Protective Coatings: CS4: Timber preservative treatment ineffective.								

Bearings

Bearing Rating: **N**

Quantity in Condition State

	Element	Defect	Description	OUM	Total	Quantity in Condition State				
						1	2	3	4	
Bearings			Bearing Type <i>None. Timber beams bear directly on timber caps.</i>	N	EA					
		2210	BRG-Movement N/A		EA					
		2240	BRG-Loss of Bearing Area N/A		EA					

Bridge ID / Structure No.	Bridge #28	Inspection Date:	11/13/2025
		Inspection TL:	Nate Miller, PE
		NBI Project No:	2503501

Substructure

Substructure Rating: **3**

Quantity in Condition State

Element	Defect	Description	OUM	Total	1	2	3	4	
Abutments	216	Substructure-Timber-Abutment <i>Timber Backwall Plank - Timber pile with backwall plank abutment.</i>	4	LF	29			29	
		TBR-Decay/ Section Loss/ Abrasion/ Wear		LF				29	
		CS3: Backwall plank minimally exposed, largely buried in earth. Assume +/-25%-50% decay/section loss.							
		4000 Settlement No readily visible signs of settlement.		LF					
		6000 Scour CS1: Both abutments beyond channel flow. No signs of undermining of backwall plank.		LF					
		Protective Coatings: CS4: Timber preservative treatment ineffective.							
	235	Substructure-Timber-Pile Cap-Abutment <i>Timber Pile Cap - Timber pile with backwall plank abutment.</i>	4	LF	29			29	
		TBR-Decay/ Section Loss/ Abrasion/ Wear		LF				29	
		CS3: Caps sound hollow with soft/easily dented shells-estimated +/- 50% decay/section loss.							
		Protective Coatings: CS4: Timber preservative treatment ineffective.							
Abutments	228	Substructure-Timber-Pile-Abutment <i>Timber Piles - Timber pile with backwall plank abutment.</i>	4	EA	10			10	
		TBR-Decay/ Section Loss/ Abrasion/ Wear		EA				10	
		[5] Bearing piles per abutment. Less than 1ft of each pile exposed. CS3: Tops of piles sound hollow with minor/moderate checking throughout. No signs of crushing. West Abutment: Estimated % Decay: S1-NE_S2-50%_S3-75%_S4-NE_S5-NE. East Abutment:-Estimated % Decay: S1-NE_S2-75%_S3-NE_S4-NE_S5-NE.							
		1140							
		Protective Coatings: CS4: Timber preservative treatment ineffective.							
Wingwalls	8400	Wingwall-Timber <i>Integral timber wingwalls. Backwall plank extends beyond bearing piles-no supplemental wingwall piles.</i>	4	EA	4			4	
		8903 WW-Deterioration CS3: Wingwall plank showing signs of incipient decay.		EA				4	
		6000 Scour CS1: Wingwalls beyond channel flow. No signs of undermining.		EA					
		Protective Coatings: CS4: Timber preservative treatment ineffective.							

Bridge ID / Structure No.	Bridge #28	Inspection Date:	11/13/2025
		Inspection TL:	Nate Miller, PE
		NBI Project No:	2503501

Pier(s)	235	Substructure-Timber-Pile Cap Pier	3	LF	60			14	46	
		<i>Timber Pile Cap - Timber pile bent pier.</i>								
		TBR-Decay/ Section Loss/ Abrasion/ Wear		LF				14	46	
	1140	CS3/CS4: Caps sound hollow throughout length estimated 50%-75% decay/section loss throughout length with +/- 75%-90% at ends. Prominent horiz. and vert. checking (>0.08") throughout. No signs of crushing. Visual only above 7ft. Pier W1/W3-Full depth vertical split through full length of cap (CS4: 30-LF). Pier W2/W4-Partial depth vertical split at ends of cap (CS4: 16-LF).								
	Protective Coatings: CS4: Timber preservative treatment ineffective.									
	228	Substructure-Timber-Pile-Pier	3	EA	20			10	10	
		<i>Timber Piles - Timber pile with backwall plank abutment.</i>								
		TBR-Decay/ Section Loss/ Abrasion/ Wear		EA				10	10	
	1140	[5] Bearing piles per pier. Visual only above 7ft. CS3/4: Piles sound hollow with prominent vertical checking/splitting throughout. Pile shells soft/easily damaged. No definitive signs of crushing. (1)-1" Deep Loose Shakes. (2)-Potential signs of initial overload distress; brooming/springy pile shell. Pier W1-Estimated % Decay: S1-75%_S2-75%_S3-75%_S4-75%_S5-75% Pier W2-Estimated % Decay: S1-75%_S2-75%_S3-50%_S4-75%_S5-50% Pier W3-Estimated % Decay: S1-90%(2) _S2-50%_S3-75%(1)_ S4-90%(2) _S5-50% Pier W4-Estimated % Decay: S1-75%(1)_S2-75%_S3-75%_S4-75%_S5-75%								
	4000	Settlement		EA						
No readily visible signs of settlement.										
6000	Scour		EA							
CS2: Less than 1' local scour within opening.										
Protective Coatings: CS4: Timber preservative treatment ineffective.										

Bridge ID / Structure No.

Bridge #28

Inspection Date: 11.13.2025

Inspection TL: Nate Miller, PE

NBI Project No: 2503501

Inspection Photos:

All photos taken at above referenced inspection date unless noted otherwise.



Photo 1 – Trail View Looking West.



Photo 2 – Trail View Looking East.



Photo 3 – Upstream Looking South.



Photo 4 – Downstream Looking North.



Photo 5 – North Railing.



Photo 6 – West Abutment.



Photo 7 – Pier W2 Looking East.



Photo 8 – Pier W1 Looking West.



Photo 9 – Pier W3 Looking East.



Photo 10 – Pier W2 Looking West.



Photo 11 – Pier W4 Looking East.



Photo 12 – East Abutment.



Photo 13 – Pier W3-Pile S4.



Photo 14 – Pier W3-Piles S3-S5.



Photo 15 – Pier W1 Cap at Piles S2-S3.



Photo 16 – S. BM-N.F.-Span 2 Over Pier W1 Looking W.



Photo 17 – N. Beam-S. Face Over West Abutment.



Photo 18 – S. Beam -S. Face. Over West Abutment .

-End of Report-