

The background of the slide is a solid orange-brown color, overlaid with several large, semi-transparent leaf patterns in various shades of brown and orange, creating a textured, autumnal effect.

# **Adventures In Sub-Slab Sampling**

# Vapor intrusion sampling was conducted at two sites in the Wausau area

- A DERP site that is currently being used as a thrift store.
- VPLE site at a closed industrial facility.

# Vapor intrusion sampling at both sites followed similar paths

- 1<sup>st</sup> tried to use temporary sample points.
- Experienced leakage problems using temporary samplers that could not be resolved.
- Had to return to the site to install permanent or permanent-like sample ports.

# Vapor intrusion sampling at both sites followed similar paths

- Showed that the installation of sampling ports is critical to collecting usable samples.
- Showed that leak testing is necessary even with the use of permanent samplers.
- Sometimes the equipment will give elevated readings with the helium meter.

# Refresher in VI Sampling



# 1) Drill Sample Location



## 2) Clean Sample Location




### 3) Install and Seal Port Installation





# Typical Sample Port Installation X-section



## 4) Leak Detection

- On-site detection using a helium shroud.



## 4) Leak Detection



- In the field used a rag soaked with a know compound such as isopropyl alcohol which is later verified by lab analysis.

## 5) Leak testing at sample port



## 6) Collect Sample



# Other Common Issues That needed to be Considered



# Other Common Issues That needed to be Considered



# Sub-Slab Sampling Sites





# 1<sup>st</sup> Attempt with Temporary Samplers



- A teflon tube is installed through the concrete and sealed.
- Vapors are drawn through the tube.
- Sounds reasonable...  
Right?

# Oh No! What Went Wrong?



# Problems with Sealing Temporary Sample Ports



- Sealing material is usually some sort of pliable material such as modeling clay, play do, bees wax, etc.
- Sealing material doesn't actually bond to the tube.
- Small gaps can form when tubing is moved/wiggled.

# Leak Testing on the Temporary Sample Ports

- DERP Site
  - Helium testing conducted
  - Leakage detected
  - Could not resolve leak problem
- VPLE Site
  - Isopropyl alcohol used to verify seal
  - Sample results contained isopropyl alcohol and other weird compounds

# VPLE Sub-slab results

	VP-1 (ug/m <sup>3</sup> )	VP-2 (ug/m <sup>3</sup> )
Analyte		
Acetone	3,100	180
Benzene	-	9.3
2-Butanone	200	-
Carbon DiSulfide	-	41
1,4 Dichlorobenzene	-	6.3
2-Propanol	160,000	89
Tetrachloroethene	250	1,700
Toluene	97	14
1,1,1- Trichloroethane	-	17

# Lesson from using temporary sample ports

- An adequate seal could not be achieved using temporary sample ports.
- The lab data was not usable (bad data).
- Site had to be re-sampled.
- Extra costs were incurred because of additional site visits.
- On-site leak testing is a good tool for avoiding bad data.

# Return trip to sample the sites

- Helium leak testing done at both sites.
- VPLE site used a home-made permanent sample port and sealed it with bees wax.
- DERP site used a commercially-made sample port and sealed it with concrete.
- And .....

# Oh No! What Went Wrong? AGAIN!



- Permanent sample ports are supposed to be fool-proof .... RIGHT?
- Both sites had leak problems on at least one permanent sample port.



# There were a number of issues at the DERP site during the second sampling event

- The ambient air registered about 10 units with the helium meter.
- The Teflon tubing registered a couple hundred units with the helium meter.
- Leak testing at the first sampling point detected helium at tens of thousands of meter units.
- Leak testing at the other sampling locations detected helium at equipment background readings.

# Sample location that failed the leak test, again



# Assembled Sample Port



# Installed Sample Port X-section




Figure 1



Thumbwheel Cap w/Chain  
*Never loose an end cap again!*

Gas Extraction  
PN: 39-64200  
*(Available Separately)*



- Foot traffic may have jarred the sample port breaking the seal between the sample port and concrete

# Sealing the thumbwheel to the floor solved the problem




Figure 1



# Sample Port used at VPLE site



# VPLE Sampling Setup





# Helium Shroud Seal



# VPLE Detected Compounds

- Dichlorodifluoromethane
- Chloromethane
- Trichlorofluoromethane
- Acetone
- Carbon Disulfide
- 1,1,2-Trichlorotrifluoromethane
- Vinyl Acetate
- MEK
- Toluene
- 2-Hexanone
- Tetrachloroethene
- Total Xylenes
- 4-Ethyltoluene
- 1,2,4-Trimethylbenzene
- 1,4-Dichlorobenzene
- Benzene
- MIBK

# Main Lessons Learned

- Temporary points are almost impossible to seal.
- Leak testing is needed on permanent points.
- Installation of sample port is critical to reliable data.
  - Choose locations that are not in major traffic areas.
  - Recess the sampling port into the slab
- The sample equipment can also give elevated readings.

# Discussion

