

DATE: August 8, 2023

FILE REF: Schoepke Site

LOCATION: Schoepke Deposit, Oneida County

WEATHER: 60 degrees & partially cloudy

ATTENDEES: Molly Gardner, DNR
John Hunt, DNR
Karl Jennrich, Oneida County Zoning Administrator
Eric Quigley, Consultant on behalf of Badger Minerals

FROM: Molly Gardner, Metallic Mining Coordinator, EA

SUBJECT: Badger Minerals 2020 Exploration Final Reclamation Inspection Report

On August 8, 2023, staff from the Wisconsin Department of Natural Resources (DNR) and a representative on behalf of Badger Minerals inspected the reclamation of Badger Minerals exploration drilling campaign which concluded in July 2020 with reclamation completed in August 2020. Five drill pads containing 6 drillholes were inspected in Sections 4 and 9, Township 35 North, Range 11 East, Town of Schoepke, Oneida County.

All access roads and drill pads were fully vegetated and in stable condition at the time of inspection. The Drillhole Filling & Sealing Reports stated neat cement grout to the surface for each of the 6 abandoned drillholes. The landscape around each of the 6 drillholes was observed to be in dry, stable condition and dominated by native upland vegetation in accordance with s. 293.13(2)(c), Wis. Stats.

Areas of observation:

- DB-01
- DB-02
- DB-03
- RB-01/02
- Stockley Creek at gravel road crossing
- LB-01
- Access roads to each drill site



Photo 1: DB-01 in center, sump to the right facing south



Photo 2: DB-01 in foreground, access to drill site (Eric Quigley, John Hunt, Karl Jennrich) facing north



Photo 3: DB-02 drill pad facing southwest



Photo 4: DB-02 at stake, sump on left facing west



Photo 5: DB-02 access road facing northeast



Photo 6: DB-03 drill pad, sump on left facing southwest



Photo 7: DB-03 access road facing north



Photo 8: Stockley Creek at gravel road crossing – water source – facing upstream to the west



Photo 9: Stockley Creek at gravel road crossing facing downstream to the east



Photo 10: RB-01 & -02 in center, sump in back facing south



Photo 11: RB-01 & -02 drill hole facing south



Photo 12: RB-01 & -02 access road facing south



Photo 13: LB-01 drill pad, sump to the back center facing west



Photo 14: LB-01 access road facing northwest