

SCHOEPKE DRILLING PROJECT RESTORATION REPORT

DATE: August 6, 2020

ON SITE: 10:15 AM

OFF SITE: 1:30 PM

WEATHER: Sunny, 70°

INDIVIDUALS ON SITE: Eric Quigley, Badger Minerals
Karl Jennrich, Oneida County Zoning Administrator
John Hunt, WDNR

I met Eric Quigley and Karl Jennrich on site to inspect restoration of drill pads. Drilling activities were completed July 3. Restoration activities took place in mid-July and early August.

Drill pads were graded using a dozer blade, drill pads were seeded and mulched. Access roads also used by logging equipment were back bladed and seeded (no mulch). Eric Quigley said seed used was DOT mix #20 as per discussions with Ben Callan.

We walked access road to each drill pad. The drill pads where restoration activities took place in July had vegetation growing (see photos from DB-1 & DB-02).

The restoration activities as stated in the notice of intent appeared to be completed.



DB-01 (at stake), Karl Jennrich (left), Eric Quigley (right). Viewing SW. 8/6/20 JTH



DB-01, Karl Jennrich standing where sump was. Viewing W. JTH 8/6/20



DB-02 at stake w/orange flag rear center. Viewing down access road SW. JTH 8/6/20



DB-02 drill pad. Viewing SW. JTN 8/6/20



DB-02, sump area on left. Viewing W. JTH 8/6/20



DB-02 access road viewing NE. JTH 8/6/20



Drill pad for DB-03. Recently seeded & mulched, borehole at upper center, sump area on left. Viewing SW. JTH 8/6/20



Closeup of DB-03, borehole at stake. JTH 8/6/20



Access road to DB-03 viewing NE. JTH 8/6/20



Northern water source at Stockley Creek, viewing SW. JTH 8/6/20





RB-01 & -02 borehole location. JTH 8/6/20



Sump of RB-01 & -02 under brush. Viewing S. JTH 8/6/20



Access road to RB-01 & -02 viewing NE. Puddles from recent heavy rains on silty soil. Viewing NE. JTH 8/6/20



Access road into RB-01 & -02 viewing NE. This road was also recently used by logging equipment. Eric Quigley (right), Karl Jennrich (center). JTH 8/6/20



Borehole LB-01, borehole location at red flag on ground (center), sump located to right of flag. Viewing W. JTH 8/6/20



Access road to LB-01. Viewing E. JTH 8/6/20